





report date: 2024-03-29

General information

| Make | VOLKSWAGEN |
|---------------------|--|
| Model | PASSAT SE BUSINESS TDI BLUEMOTION TECHNOLOGY |
| Colour | Grey |
| Year of manufacture | 2017 |
| Top speed | 128 mph |
| 0 - 100 km/h | 10.8 seconds |
| 0 - 60 mph | 10.8 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 88 kW / 120 HP / 118 BHP |
|-------------------------|--------------------------|
| Max. torque | 250 Nm at 1.750 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 60.1 mpg |
| Consumption extra urban | 78.5 mpg |
| Consumption combined | 70.6 mpg |
| CO2 emission | 105 g/km |
| CO2 label | В |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2022-04-18

Pictures 21

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

| MOT expiry date | 2024-12-13 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 4 |
| Failed MOT tests | 0 |
| Total advice items | 14 |
| Total items failed | 0 |

| MOT #4 | 2023-12-13 12:39 |
|--|------------------|
| MOT test number | 244334483922 |
| Result | ✓ Passed |
| Next expiry date | 2024-12-13 |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Nearside Front Tyre slightly damaged (5.2.3 (d) (ii)) | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #3 | | 2022-12-14 10:40 |
|----------|--|------------------|
| MOT test | number | 801227043906 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #2 2021-12-01 17:43

MOT test number 683927447381

Result ✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2020-12-07 10:03

MOT test number 905007061367

Result ✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 October |
|------------------|-----------------------|
| Days left | 155 |
| MOT expiry date | 13 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|------------|
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

Owner history

| owner mistery | |
|---|-------------|
| For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here. | |
| *************************************** | |
| ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | |
| *************************************** | |
| | |
| THE REAL PROPERTY OF THE PERTY | |
| | |
| ************************************** | |
| Plate changes | More info > |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | |
| Current registration | NK SIN |
| Plate since | |
| Current registration | UK UK |
| Plate since | |

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2017-12-14 |
| Last registration | 2023-12-13 |
| Complete history | See info |



| Registration #1 | 2017-12-14 | 15 mi |
|-----------------|------------|-----------|
| Registration #2 | 2020-12-07 | 54.371 mi |
| Registration #3 | 2021-12-01 | 57.586 mi |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 0.777-46 |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 85% |
| Children | 87% |
| Pedestrian | 66% |
| Safety systems | 76% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| Width | 1832 mm |
|---------------------|---------|
| Height | 1456 mm |
| Length | 4767 mm |
| Wheel base | 2791 mm |
| Kerb weight | 1444 kg |
| Max. allowed weight | 1990 kg |

Additional information

| Fuel tank capacity | 59 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| CarChack co.uk | 220 11/11 |

CarCheck.co.uk page 11/11

| Number of seats | 5 |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | DCXA381162 |