





General information

Make	AUDI
Model	A3 TDI SPORT
Colour	Silver
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	64.2 mpg
Consumption combined	53.3 mpg



MOT history

MOT #17	2023-01-05 15:25
MOT test number	367212835151
Result	✓ Passed
Next expiry date	2024-01-04
Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	
Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16	2022-12-20 17:10
MOT test number	770124692837
Result	🗙 Failed
Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	
Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	Inner sidewall
Advice Front Brake disc worn, but not excessively Both fronts (1.1.14 (a) (i))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail (ii))Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingres	ss of dirt (5.3.4 (b)
Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))	
FailNearside Front Headlamp aim too low (4.1.2 (a))	
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail (b) (ii))Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingr	ress of dirt (5.3.4
FailNearside Front Suspension arm ball joint dust cover no longer prevents the ingress(ii))	of dirt (5.3.4 (b)



SD57UCF
report date: 2024-03-29

MOT #15	2021-12-06 11:02	
MOT test number	803994012581	
Result	✓ Passed	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))		
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

MOT #14		2020-12-05 09:44
MOT test	number	584824709506
Result		✓ Passed
Advice	Nearside Front tyre slight wear on edhe	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #13	2019-11-16 11:43
MOT test number	151060897144
Result	✓ Passed
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2019-11-16 11:43	
MOT test number	403175090445	
Result	× Failed	
Pass with rectification lamps (4.7.1 (b) (ii))	Nearside Registration plate lamp inoperative in the case of a single lamp or all	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass with rectification lamps (4.7.1 (b) (ii))	Offside Registration plate lamp inoperative in the case of a single lamp or all	





MOT #11	2018-12-03 10:24
MOT test number	304754697320
Result	✓ Passed
Advice Nearside Non obligatory mirror damaged	
Minor Registration plate lamp inoperative in the case of multiple lamps or light	sources (4.7.1 (b) (i))

MOT #10		2017-12-06 13:24
MOT test	number	113870110761
Result		✓ Passed
Advice	Tyre worn close to the legal limit Both front wearing on edge's (4.1.E.1)	
Advice	Offside rear number plate light unit damaged.	

МОТ #9	2016-11-16 14:32
MOT test number	504981220438
Result	✓ Passed

MOT #8	2015-11-20 10:48
MOT test number	458666085466
Result	✓ Passed

MOT #7	2014-11-19 08:45
MOT test number	466243124448
Result	✓ Passed

МОТ #6	2013-11-06 10:59
MOT test number	398160613371
Result	✓ Passed





MOT #5	2012-10-19 16:25
MOT test number	508953692225
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
MOT #4	2012-10-19 14:31
MOT test number	388303792296
Result	🗙 Failed
Fail Nearside Rear Rear position lamp(s) not working (1.1.A.3b)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Rear Stop lamp not working (1.2.1b)	

МОТ #3	2011-11-05 12:03
MOT test number	465139001337
Result	✓ Passed
Notice Offside front wiper slight smeer	

MOT #2	2011-11-05 10:48
MOT test number	215029101322
Result	🗙 Failed
FailOffside Front Tyre has a bulge, caused by separation or partial failure of itsNoticeOffside front wiper slight smeer	structure (4.1.D.1b)

MOT #1	2010-11-12 12:41
MOT test number	831446210326
Result	✓ Passed





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et a
Date	*
Category	AMP
Туре	

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-10-15
Last registration	2023-01-05
Complete history	<u>See info</u>



Registration #1	2007-10-15	15 mi
Registration #2	2010-11-12	63.593 mi
Registration #3	2011-11-05	70.656 mi
Registration #4	2011-11-05	70.656 mi
Registration #5	2012-10-19	77.510 mi
Registration #6	2012-10-19	77.519 mi
Registration #7	2013-11-06	84.425 mi
Registration #8	2014-11-19	93.139 mi
Registration #9	2015-11-20	100.897 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		10. 100 aut





Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
60569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1765 mm
Height	1421 mm
Length	4203 mm
Wheel base	2578 mm
Kerb weight	1295 kg
Max. allowed weight	1840 kg
Additional information	
Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	BXE 665529