






report date: 2024-03-28

## General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI
Colour	White
Year of manufacture	2011
Top speed	93 mph
0 - 60 mph	16.7 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	74 BHP
Max. torque	225 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	49.6 mpg



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history

		1
ᆮ	HLIV	-

Lifety 1	
Date	2021-09-09
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

# **MOT** history

Fail

**Advice** 

MOT expiry date	2023-11-25
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	14
Total items failed	4

MOT #11		2022-11-25 13:51
MOT test	number	316122694633
Result		✓ Passed
Next expi	ry date	2023-11-25
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))
Advice	Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (	ii))

MOT #10	2021-11-26 12:11
MOT test number	739390500460
Result	✓ Passed
MOT #9	2021-11-24 10:47
MOT test number	471183257936
Result	<b>×</b> Failed
<b>Fail</b> Offside Rear Leaf spring fractured (5.3.1 (b) (i))	

Trailer electrical socket (13 pin) not operating the trailer lamps as intended (4.10 (c) (i))

Nearside Front Service brake binding but not excessively (1.2.1 (f))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8 2021-02-05 09:12

**MOT test number** 319444050776

**Result** 
✓ Passed

**MOT #7** 2020-01-27 09:12

**MOT test number** 508125479003

**Result** 
✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #6 2019-02-05 15:05

**MOT test number** 302917491598

Minor Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #5 2019-02-04 13:39

MOT test number 379666607123

Result × Failed

Minor Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Fail** Offside Front Suspension arm pin or bush excessively worn rear wishone bush (5.3.4 (a) (i))

Fail Nearside Front Suspension arm pin or bush excessively worn rear wishbone bush (5.3.4 (a) (i))

MOT #4 2018-01-16 14:25

MOT test number 105052449264

**Result** 
✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Crack in screen

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3 2017-01-19 09:38

**MOT test number** 144453836376

MOT #2 2016-02-08 18:11

MOT test number 121034189056

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1 2014-12-19 12:24

**MOT test number** 399763854361

Result \( \sqrt{Passed} \)

**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)

Advice Front registration plate delaminated but not likely to be misread (6.3.1d)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status Valid until 1 November

Days left 186

MOT expiry date 25 November 2023

Full MOT history See MOT history

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.


#### Damage 1

Date	
Category	
Туре	
Damago 2	

Damage 2

Date
Category

**Type** 



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
*********	
***************************************	
***********	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-12-30
Last registration	2022-11-25
Complete history	See info



Registration #1	2011-12-30	18 mi
Registration #2	2014-12-19	48.047 mi
Registration #3	2016-02-08	63.141 mi
Registration #4	2017-01-19	69.544 mi
Registration #5	2018-01-16	74.848 mi
Registration #6	2019-02-04	81.364 mi
Registration #7	2019-02-05	81.364 mi
Registration #8		77,777 66
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		D.777 es
Registration #13		0.777-44

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2062 mm
Height	1836 mm
Length	4876 mm
Kerb weight	1475 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	CAYEK18667

CarCheck.co.uk page 12/12