





report date: 2024-03-28

#### General information

Make	VOLVO
Model	V60 D3 INSCRIPTION
Colour	White
Year of manufacture	2017
Top speed	130 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	108 g/km
CO2 label	В



CarCheck.co.uk page 1/12



## Internet history

#### Entry 2

Date 2021-06-30

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk


Entry 1


Date	2021-06-29
Pictures	12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



**MOT** history

MOT expiry date	2025-03-28
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	7
Total items failed	6

MOT #9	2024-02-29 09:35
MOT test number	995351724047
Result	✓ Passed
Next expiry date	2025-03-28

MOT #8	2024-02-26 17:08	
MOT test number	483678517869	
Result	<b>X</b> Failed	
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))		
<b>Fail</b> Offside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))		
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))		
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

MOT #7	2023-03-24 15:11
MOT test number	303646756163
Result	<b>✓</b> Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  Advice Nearside Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #6 2022-03-29 12:33

**MOT test number** 550691544283

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #5** 2022-03-25 09:57

MOT test number 890155405573

Result X Failed

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2021-03-08 09:54

**MOT test number** 724460918498

MOT #3 2021-03-08 09:54

MOT test number 902892806129

**Result** X Failed

Pass with rectification Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Pass with rectification Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #2** 2020-03-09 09:50

**MOT test number** 258063659299

Result 

Passed

CarCheck.co.uk page 4/12



MOT #1 2019-03-19 13:39

**MOT test number** 938216217247

**Result** ✓ Passed

CarCheck.co.uk page 5/12



#### Tax & MOT check





Tax status

Days left

63 days too late

MOT expiry date

28 March 2025

Full MOT history

See MOT history

#### Tax calculation

-	
Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
*********	
********	
***************************************	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	NK AND
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2017-07-21
Last registration	2024-02-29
Complete history	See info



Registration #1	2017-07-21	12 mi
Registration #2	2019-03-19	4.804 mi
Registration #3	2020-03-09	49.761 mi
Registration #4	2021-03-08	80.055 mi
Registration #5	2021-03-08	80.055 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71,777 es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditionin
50295	
50482	
50501	
60566	
60567	
60569	

## Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



## Dimensions & weight

Width	1857 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1439 kg
Max. allowed weight	1995 kg

# Additional information

Fuel tank capacity	62 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	12/12

Number of axles2Engine number1997496