




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE 5STR
Colour	Black
Year of manufacture	2007
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	156 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-06-19
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-03
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	7
Total items failed	9

MOT #19	2024-01-04 12:15
MOT test number	603920234241
Result	✓ Passed
Next expiry date	2025-01-03

MOT #18	2023-12-18 15:40
MOT test number	373602754315
Result	✗ Failed
Fail	Offside Front Suspension arm pin or bush excessively worn marked in white (5.3.4 (a) (i))
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt

MOT #17	2023-12-06 12:10
MOT test number	182379537559
Result	✗ Failed
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Offside Front Suspension arm pin or bush excessively worn marked in white (5.3.4 (a) (i))

MOT #16	2022-11-18 11:09
MOT test number	739232043975
Result	✓ Passed
Advice	Small chips in windscreen

**MOT #15** 2022-11-05 13:24**MOT test number** 788632415965**Result** ✗ Failed**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure outer (5.2.3 (d) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Small chips in windscreen**Fail** Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt both front (5.3.4 (b) (ii))**MOT #14** 2021-05-15 13:37**MOT test number** 923019293293**Result** ✓ Passed**MOT #13** 2020-05-19 17:22**MOT test number** 446059573812**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2019-05-02 17:19**MOT test number** 885065429490**Result** ✓ Passed**MOT #11** 2019-05-02 17:19**MOT test number** 680576671899**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))

**MOT #10** 2018-05-19 14:33**MOT test number** 385959174401**Result** ✓ Passed**MOT #9** 2017-05-20 15:27**MOT test number** 444506250134**Result** ✓ Passed**MOT #8** 2016-05-12 17:33**MOT test number** 880990725088**Result** ✓ Passed**MOT #7** 2015-05-12 11:49**MOT test number** 179702435152**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-05-21 10:55**MOT test number** 397651944112**Result** ✓ Passed**MOT #5** 2014-05-21 10:55**MOT test number** 587701944160**Result** ✗ Failed**Pass with rectification** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)



MOT #4	2013-04-23 13:51
MOT test number	418223413190
Result	✓ Passed
MOT #3	2012-04-28 12:01
MOT test number	309999612158
Result	✓ Passed
MOT #2	2011-04-27 15:36
MOT test number	658297911165
Result	✓ Passed
MOT #1	2010-03-15 11:18
MOT test number	182324770062
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
3 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	3 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-29
Last registration	2024-01-04
Complete history	See info



Registration #1	2007-03-29	6 mi
Registration #2	2010-03-15	75.103 mi
Registration #3	2011-04-27	87.504 mi
Registration #4	2012-04-28	98.528 mi
Registration #5	2013-04-23	108.449 mi
Registration #6	2014-05-21	119.234 mi
Registration #7	2015-05-12	125.003 mi
Registration #8	2016-05-12	137.476 mi
Registration #9	2017-05-20	159.931 mi
Registration #10	2018-05-19	166.435 mi
Registration #11	2019-05-20	171.277 mi
Registration #12	2020-05-20	171.277 mi
Registration #13	2021-05-20	171.277 mi
Registration #14	2022-05-20	171.277 mi
Registration #15	2023-05-20	171.277 mi
Registration #16	2024-01-04	171.277 mi
Registration #17	2024-01-04	171.277 mi
Registration #18	2024-01-04	171.277 mi
Registration #19	2024-01-04	171.277 mi
Registration #20	2024-01-04	171.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BXE 371313