



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK200 AVANTGARDE
Colour	Silver
Year of manufacture	2004
Top speed	142 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	31.7 mpg
CO2 emission	206 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-02
Pictures	3
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-22
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	50
Total items failed	2

MOT #23	2024-02-23 15:35
MOT test number	243744348876
Result	✓ Passed
Next expiry date	2025-02-22
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #22	2024-02-22 11:43
MOT test number	712112862501
Result	✗ Failed
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21	2022-12-16 12:32
MOT test number	608493644343
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20** 2021-12-16 12:59**MOT test number** 877228569859**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #19** 2020-12-08 16:48**MOT test number** 531760416087**Result** ✓ Passed**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #18**

2020-12-07 11:54

**MOT test number**

484327636409

**Result**

✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- MAJOR** Nearside Front Headlamp levelling device inoperative (4.1.5 (a))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- MAJOR** Nearside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))
- MAJOR** Offside Front Headlamp levelling device inoperative (4.1.5 (a))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #17**

2019-12-09 09:06

**MOT test number**

125832423941

**Result**

✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #16** 2019-12-07 13:54**MOT test number** 180076090698**Result** ✗ Failed

**MAJOR** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MAJOR** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #15** 2018-12-03 16:27**MOT test number** 912766141364**Result** ✓ Passed**MOT #14** 2018-11-30 13:41**MOT test number** 115319364092**Result** ✗ Failed

**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #13** 2017-12-21 11:26**MOT test number** 148427798598**Result** ✓ Passed**MOT #12** 2016-12-24 09:44**MOT test number** 776084965460**Result** ✓ Passed

**MOT #11** 2015-12-03 09:56**MOT test number** 344837839311**Result** ✓ Passed**MOT #10** 2015-01-16 10:18**MOT test number** 867146015033**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Front Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2)**MOT #9** 2014-01-28 13:45**MOT test number** 346858424051**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Slight damage to windscreen**MOT #8** 2014-01-24 09:01**MOT test number** 789424224046**Result** ✗ Failed**Fail** Offside Headlamp cleaning device inoperative (1.7.2)**Fail** Nearside Headlamp cleaning device inoperative (1.7.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Slight damage to windscreen

**MOT #7** 2013-01-14 08:50**MOT test number** 556214313004**Result** ✓ Passed**MOT #6** 2012-01-12 08:57**MOT test number** 117322712026**Result** ✓ Passed**MOT #5** 2011-01-13 11:43**MOT test number** 965803211061**Result** ✓ Passed**MOT #4** 2010-01-28 08:29**MOT test number** 403678920072**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2009-01-20 08:52**MOT test number** 590370629072**Result** ✓ Passed**Notice** Front radius arm bushes beginning to deteriorate.**MOT #2** 2008-02-08 12:52**MOT test number** 694879038048**Result** ✓ Passed**MOT #1** 2007-06-25 12:05**MOT test number** 540566877107**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
22 February 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	22 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01
Current registration	 <b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-07-20
Last registration	2024-02-23
Complete history	<a href="#">See info</a>



Registration #1	2004-07-20	24 mi
Registration #2	2007-06-25	29.089 mi
Registration #3	2008-02-08	35.744 mi
Registration #4	2009-01-20	41.095 mi
Registration #5	2010-01-28	47.378 mi
Registration #6	2011-01-13	53.542 mi
Registration #7	2012-01-12	63.017 mi
Registration #8	2013-01-14	69.907 mi
Registration #9	2014-01-24	76.798 mi
Registration #10	2014-01-28	76.940 mi
Registration #11	2015-01-16	83.716 mi
Registration #12	2015-12-03	93.667 mi
Registration #13	2016-12-24	98.879 mi
Registration #14	2019-05-20	101.377 mi
Registration #15	2019-05-20	101.377 mi
Registration #16	2019-05-20	101.377 mi
Registration #17	2019-05-20	101.377 mi
Registration #18	2019-05-20	101.377 mi
Registration #19	2019-05-20	101.377 mi
Registration #20	2019-05-20	101.377 mi
Registration #21	2019-05-20	101.377 mi
Registration #22	2019-05-20	101.377 mi
Registration #23	2019-05-20	101.377 mi
Registration #24	2019-05-20	101.377 mi
Registration #25	2019-05-20	101.377 mi



Dimensions & weight

Width	1740 mm
Height	1413 mm
Length	4638 mm
Wheel base	2715 mm
Kerb weight	1615 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	27194030339660