



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO AUTHENTIQUE 16V
Colour	Blue
Year of manufacture	2008
Top speed	96 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	105 Nm at 3.500 rpm
Engine capacity	1.149 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	163 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-30
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-31
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	25
Total items failed	8

MOT #15 2023-10-31 10:16

MOT test number 596505930910

Result ✓ Passed

Next expiry date 2024-10-31

Advice Rear Exhaust mounting defective (6.1.2 (a))**Advice** Nearside Front Road wheel slightly distorted Rim damage (5.2.2 (c) (i))

MOT #14 2022-10-29 09:29

MOT test number 855477182588

Result ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13 2022-10-28 12:43

MOT test number 351286888676

Result ✗ Failed**Fail** Rear Service brake excessively binding O/S & N/S (1.2.1 (f))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #12** 2021-11-01 15:22**MOT test number** 301404051774**Result** ✓ Passed**MOT #11** 2020-09-11 09:57**MOT test number** 165152017985**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Damage to nearside rear light unit**MOT #10** 2020-09-08 14:53**MOT test number** 657470354670**Result** ✗ Failed**Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Damage to nearside rear light unit**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Front Power steering component leaking (2.1.5 (a))**Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #9** 2019-09-05 14:20**MOT test number** 990744754476**Result** ✓ Passed

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing run flat damage (5.2.3 (d) (ii))

MOT #8 2018-09-06 08:26**MOT test number** 153227113944**Result** ✓ Passed

Advice Nearside Rear light unit damaged

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear run flat damage

Advice Offside Rear Tyre slightly damaged/valve stem damaged (5.2.3 (d) (i))

MOT #7 2017-09-05 11:01**MOT test number** 157350766219**Result** ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit worn to 3.0 mm and outer sidewall damaged 175/65 x 14 82 h (4.1.E.1)

Advice Nearside Rear tyre outer sidewall damaged

Advice Offside Front Tyre worn close to the legal limit worn to 3.0 mm (4.1.E.1)

**MOT #6** 2017-09-05 07:41**MOT test number** 303913863994**Result** ✗ Failed**Advice** Nearside Rear tyre outer sidewall damaged**Advice** Nearside Front Tyre worn close to the legal limit worn to 3.0 mm and outer sidewall damaged
175/65 x 14 82 h (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit worn to 3.0 mm (4.1.E.1)**MOT #5** 2016-09-09 11:07**MOT test number** 417375671087**Result** ✓ Passed**MOT #4** 2016-09-09 11:07**MOT test number** 775654279910**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #3** 2014-10-08 10:59**MOT test number** 265571784292**Result** ✓ Passed**MOT #2** 2013-09-11 10:47**MOT test number** 249354153288**Result** ✓ Passed**MOT #1** 2011-10-17 16:18**MOT test number** 968190791288**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
31 October 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	31 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-12-18
Last registration	2023-10-31
Complete history	See info



Registration #1	2008-12-18	22 mi
Registration #2	2011-10-17	12.294 mi
Registration #3	2013-09-11	21.480 mi
Registration #4	2014-10-08	27.782 mi
Registration #5	2016-09-09	38.215 mi
Registration #6	2016-09-09	38.215 mi
Registration #7	2017-09-05	45.071 mi
Registration #8	2017-09-05	45.071 mi
Registration #9	2018-09-06	52.186 mi
Registration #10	2019-09-06	59.299 mi
Registration #11	2020-09-06	66.412 mi
Registration #12	2021-09-06	73.525 mi
Registration #13	2022-09-06	80.638 mi
Registration #14	2023-09-06	87.751 mi
Registration #15	2023-09-06	87.751 mi
Registration #16	2023-10-31	87.751 mi
Registration #17	2023-10-31	87.751 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1672 mm
Height	1855 mm
Length	4035 mm
Wheel base	2605 mm
Kerb weight	1045 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	F054503