



**LR06EKB**


report date: 2024-03-29

General information

Make	JAGUAR
Model	XK CONVERTIBLE
Colour	Grey
Year of manufacture	2006
Top speed	155 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	294 BHP
Max. torque	411 Nm at 4.100 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.5 mpg
Consumption extra urban	33.6 mpg
Consumption combined	25.0 mpg
CO2 emission	269 g/km
CO2 label	M





Internet history

Entry 2


Date	2022-10-01
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-06-25
Pictures	45
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-03-14
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	26
Total items failed	4

MOT #18	2024-02-27 13:02
MOT test number	302013996119
Result	✓ Passed
Next expiry date	2025-03-14
Minor	Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #17	2024-02-27 11:05
MOT test number	147841965571
Result	✗ Failed
Minor	Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Fail	Offside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #16	2023-03-15 15:15
MOT test number	181082931458
Result	✓ Passed
Minor	Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #15** 2022-01-31 12:59**MOT test number** 297766824108**Result** ✓ Passed

**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement outer (5.3.4 (a) (i))

**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement inner rear (5.3.4 (a) (i))

**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement outer (5.3.4 (a) (i))

**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement inner rear (5.3.4 (a) (i))

**Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #14** 2021-01-12 15:45**MOT test number** 571179411660**Result** ✓ Passed**MOT #13** 2020-01-22 10:10**MOT test number** 583527134813**Result** ✓ Passed

**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**MOT #12** 2020-01-22 10:10**MOT test number** 143590012566**Result** ✗ Failed

**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

**MOT #11** 2019-01-23 17:44**MOT test number** 440495251295**Result** ✓ Passed

**MOT #10** 2017-09-27 14:34**MOT test number** 478752145331**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2016-05-26 10:40**MOT test number** 732233380979**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2015-05-12 17:29**MOT test number** 235342435403**Result** ✓ Passed**MOT #7** 2013-09-09 15:41**MOT test number** 319912353437**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #6** 2013-01-15 10:14**MOT test number** 545835113089**Result** ✓ Passed

**MOT #5** 2013-01-14 14:35**MOT test number** 755244713059**Result** ✗ Failed**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-01-27 07:12**MOT test number** 828957622005**Result** ✓ Passed**MOT #3** 2011-06-13 16:34**MOT test number** 558404361149**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #2** 2010-05-20 14:59**MOT test number** 241780540117**Result** ✓ Passed**MOT #1** 2009-05-06 15:38**MOT test number** 410276229111**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
14 March 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	14 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	M
<b>Single payment (12 months)</b>	£ 695,00,-
<b>Single six month payment</b>	£ 382,25,-
<b>Total payable by 12 monthly instalments</b>	£ 729,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>LR06EKB</b>
Plate since	2024-03-29
Current registration	<b>LR06EKB</b>
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-05-03
Last registration	2024-02-27
Complete history	<a href="#">See info</a>



Registration #1	2006-05-03	22 mi
Registration #2	2009-05-06	17.286 mi
Registration #3	2010-05-20	21.632 mi
Registration #4	2011-06-13	26.615 mi
Registration #5	2012-01-27	28.812 mi
Registration #6	2013-01-14	49.983 mi
Registration #7	2013-01-15	49.983 mi
Registration #8	2013-09-09	58.755 mi
Registration #9	2015-05-12	61.398 mi
Registration #10	2016-05-26	65.376 mi
Registration #11	2017-09-27	76.632 mi
Registration #12	2019-05-20	76.632 mi
Registration #13	2019-05-20	76.632 mi
Registration #14	2019-05-20	76.632 mi
Registration #15	2019-05-20	76.632 mi
Registration #16	2019-05-20	76.632 mi
Registration #17	2019-05-20	76.632 mi
Registration #18	2019-05-20	76.632 mi
Registration #19	2019-05-20	76.632 mi
Registration #20	2019-05-20	76.632 mi
Registration #21	2019-05-20	76.632 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1329 mm
Length	4791 mm
Wheel base	2752 mm
Kerb weight	1815 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	06032910285G