



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CADDY C20 PLUS SDI
Colour	Blue
Year of manufacture	2009
Top speed	88 mph
0 - 60 mph	20.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	140 Nm at 2.200 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-13
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)



## MOT history

MOT expiry date	2024-08-01
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	13
Total items failed	11

MOT #15	2023-07-28 12:53
MOT test number	205164558291
Result	✓ Passed
Next expiry date	2024-08-01

MOT #14	2022-07-28 07:16
MOT test number	481889754211
Result	✓ Passed

MOT #13	2021-08-02 12:44
MOT test number	651036924699
Result	✓ Passed

**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #12	2020-07-16 15:37
MOT test number	921696719000
Result	✓ Passed

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #11** 2020-07-15 10:32**MOT test number** 555610491275**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear bush splitting (5.3.4 (a) (i))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush splitting (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Rear Exhaust has a major leak of exhaust gases rear silencer (6.1.2 (a))**MOT #10** 2019-07-17 09:06**MOT test number** 948053807422**Result** ✓ Passed**MOT #9** 2018-07-24 15:31**MOT test number** 878005638362**Result** ✓ Passed**MOT #8** 2018-07-21 07:40**MOT test number** 863509710900**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar pin or bush excessively worn D-Bush (5.3.4 (a) (i))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #7** 2017-07-14 08:08**MOT test number** 602343794143**Result** ✓ Passed



<b>MOT #6</b>	2016-07-04 08:52
<b>MOT test number</b>	167771525812
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #5</b>	2015-07-09 10:02
<b>MOT test number</b>	938960095184
<b>Result</b>	✓ Passed
<b>Notice</b>	Rear tyres cracking on tread
<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #4</b>	2014-07-11 13:56
<b>MOT test number</b>	208122094176
<b>Result</b>	✓ Passed
<b>Notice</b>	Rear tyres cracking on tread

<b>MOT #3</b>	2014-07-11 11:15
<b>MOT test number</b>	897602394129
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Windscreen wiper not operating automatically when switched on (8.2.1b)
<b>Fail</b>	Offside Windscreen washer provides insufficient washer liquid (8.2.3)
<b>Fail</b>	Nearside Windscreen wiper not operating automatically when switched on (8.2.1b)
<b>Fail</b>	Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
<b>Notice</b>	Rear tyres cracking on tread



MOT #2	2013-07-17 10:26
MOT test number	155738893180
Result	✓ Passed
Notice	Nearside rear tyre sidewall slightly perished
Notice	Park brake leaver release button missing

MOT #1	2012-08-14 10:29
MOT test number	119097722204
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
1 August 2024

<b>Tax status</b>	Valid until 1 November
-------------------	------------------------

<b>Days left</b>	187
------------------	-----

<b>MOT expiry date</b>	1 August 2024
------------------------	---------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>DX09PYL</b>
Plate since	2019-06-29
Current registration	 <b>DX09PYL</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-08-17
Last registration	2023-07-28
Complete history	<a href="#">See info</a>



Registration #1	2009-08-17	17 mi
Registration #2	2012-08-14	23.065 mi
Registration #3	2013-07-17	27.491 mi
Registration #4	2014-07-11	36.667 mi
Registration #5	2014-07-11	36.667 mi
Registration #6	2015-07-09	46.810 mi
Registration #7	2016-07-04	57.303 mi
Registration #8	2017-07-14	70.051 mi
Registration #9	2018-07-21	82.849 mi
Registration #10	2019-07-21	95.647 mi
Registration #11	2020-07-21	108.445 mi
Registration #12	2021-07-21	121.243 mi
Registration #13	2022-07-21	134.041 mi
Registration #14	2023-07-21	146.839 mi
Registration #15	2024-07-21	159.637 mi
Registration #16	2025-07-21	172.435 mi
Registration #17	2026-07-21	185.233 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1833 mm
Length	4405 mm
Kerb weight	1465 kg
Max. allowed weight	2232 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2

**Number of axles**

2

**Engine number**

BST0094691