



report date: 2024-03-29

## General information

Make	VOLVO
Model	V70 D4 SE LUX
Colour	Silver
Year of manufacture	2015
Top speed	137 mph
0 - 60 mph	8.1 seconds
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	122 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-04-28
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



## MOT history

MOT expiry date	2024-09-08
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #8	2023-08-30 10:47
MOT test number	912285751725
Result	✓ Passed
Next expiry date	2024-09-08

MOT #7	2022-09-09 08:21
MOT test number	398365577696
Result	✓ Passed
Advice	Nearside Rear wheel rim has probable welding repair

MOT #6	2022-09-09 08:21
MOT test number	978022925969
Result	✗ Failed
Advice	Nearside Rear wheel rim has probable welding repair
Pass with rectification	Nearside Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #5	2021-10-25 15:52
MOT test number	176700471612
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view Minor stone chips on windscreen (3.2 (a) (i))
Advice	Brake pedal anti slip device slightly worn



MOT #4 2020-10-22 09:57

MOT test number 191569444649

Result ✓ Passed

MOT #3 2019-10-09 10:18

MOT test number 212917201467

Result ✓ Passed

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2 2018-10-26 14:09

MOT test number 223129969630

Result ✓ Passed

**Advice** Brake pedal anti-slip worn on edge, however secure

MOT #1 2018-10-26 14:09

MOT test number 344842260236

Result ✗ Failed

**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

**Advice** Brake pedal anti-slip worn on edge, however secure



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
8 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	8 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>WF65BWY</b>
Plate since	2019-09-29
Current registration	<b>WF65BWY</b>
Plate since	2019-09-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-03
Last registration	2023-08-30
Complete history	<a href="#">See info</a>



Registration #1	2015-09-03	27 mi
Registration #2	2018-10-26	77.662 mi
Registration #3	2018-10-26	77.662 mi
Registration #4	2019-10-09	84.700 mi
Registration #5	2020-10-22	91.913 mi
Registration #6	2021-10-22	91.913 mi
Registration #7	2021-10-22	91.913 mi
Registration #8	2021-10-22	91.913 mi
Registration #9	2021-10-22	91.913 mi
Registration #10	2023-08-30	91.913 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2106 mm
Height	1547 mm
Length	4814 mm
Wheel base	2816 mm
Kerb weight	1757 kg
Max. allowed weight	2290 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1290784