




report date: 2024-03-29

General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Blue
Year of manufacture	2005
Top speed	141 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	205 BHP
Max. torque	435 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.2 mpg
CO2 emission	208 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-14
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2023-10-26
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	23
Total items failed	23

MOT #21	2022-10-21 09:21
MOT test number	145331839003
Result	✓ Passed
Next expiry date	2023-10-26

MOT #20	2021-10-27 09:41
MOT test number	347322815858
Result	✓ Passed

MOT #19	2020-07-16 10:52
MOT test number	408445549661
Result	✓ Passed

- Minor

Front Headlamp lens slightly defective both (4.1.1 (b) (i))
- Advice

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #18**

2020-07-14 16:17

**MOT test number**

470243393540

**Result****✗ Failed**

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Brake servo inoperative (1.1.10 (a) (ii))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Minor** Front Headlamp lens slightly defective both (4.1.1 (b) (i))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #17**

2020-07-03 10:54

**MOT test number**

912520669552

**Result****✗ Failed**

- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Air/vacuum reservoir leaking Brake servo not working (1.1.9 (a) (ii))
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Fail** Windscreen washer not working (3.5 (a))

**MOT #16** 2019-03-22 13:05**MOT test number** 719614148386**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 245/40R18 Dunlop (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15** 2018-03-20 11:43**MOT test number** 443959300238**Result** ✓ Passed

- Advice** Oil leak

**MOT #14** 2017-03-28 15:37**MOT test number** 391984677059**Result** ✓ Passed

- Advice** Oil leak

**MOT #13** 2017-03-27 16:20**MOT test number** 369934960614**Result** ✗ Failed

- Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Oil leak
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #12** 2016-04-20 13:06**MOT test number** 889623540959**Result** ✓ Passed**MOT #11** 2016-04-18 07:35**MOT test number** 608776667942**Result** ✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Electronic parking brake warning indicates a malfunction (3.1.7)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Nearside Headlamp aim too low (1.8)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)

**MOT #10** 2015-03-12 15:09**MOT test number** 716431475013**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #9** 2014-03-12 09:58**MOT test number** 527961274096**Result** ✓ Passed

**MOT #8** 2014-03-03 12:13**MOT test number** 909262064008**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #7** 2013-03-02 11:36**MOT test number** 176941063409**Result** ✓ Passed**MOT #6** 2012-03-02 09:28**MOT test number** 498732462069**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #5** 2011-02-04 11:53**MOT test number** 117815531022**Result** ✓ Passed**MOT #4** 2010-02-18 12:16**MOT test number** 633659540049**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)



MOT #3	2009-02-11 14:16
MOT test number	233672549007
Result	✓ Passed
MOT #2	2008-02-15 12:36
MOT test number	920486348079
Result	✓ Passed
MOT #1	2008-02-15 12:36
MOT test number	760446648092
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too low (1.8)



Tax & MOT check

✕  
Untaxed

Tax expired:  
11 November 2022

✕  
MOT

Expired:  
26 October 2023

Tax status	Expired at 11 November 2022
Days left	536 days too late
MOT expiry date	26 October 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-03-01
Last registration	2022-10-21
Complete history	<a href="#">See info</a>



Registration #1	2005-03-01	14 mi
Registration #2	2008-02-15	16.088 mi
Registration #3	2009-02-11	21.782 mi
Registration #4	2010-02-18	29.668 mi
Registration #5	2011-02-04	35.885 mi
Registration #6	2012-03-02	45.701 mi
Registration #7	2013-03-02	53.557 mi
Registration #8	2014-03-03	62.934 mi
Registration #9	2014-03-12	62.962 mi
Registration #10	2015-03-12	75.286 mi
Registration #11	2016-04-18	83.996 mi
Registration #12	2016-05-20	91.277 mi
Registration #13	2016-06-20	98.558 mi
Registration #14	2016-07-20	105.839 mi
Registration #15	2016-08-20	113.120 mi
Registration #16	2016-09-20	120.401 mi
Registration #17	2016-10-20	127.682 mi
Registration #18	2016-11-20	134.963 mi
Registration #19	2016-12-20	142.244 mi
Registration #20	2017-01-20	149.525 mi
Registration #21	2017-02-20	156.806 mi
Registration #22	2017-03-20	164.087 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1818 mm
Height	1447 mm
Length	4905 mm
Wheel base	2909 mm
Kerb weight	1790 kg
Max. allowed weight	2255 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	00099937B