



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX LX TDCI
Colour	Grey
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-18
Pictures	3
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #16</b>	2022-03-10 17:43
<b>MOT test number</b>	151552600810
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-03-09

<b>MOT #15</b>	2021-02-08 16:38
<b>MOT test number</b>	510257055710
<b>Result</b>	✓ Passed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))

**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

<b>MOT #14</b>	2020-02-10 16:26
<b>MOT test number</b>	545735054312
<b>Result</b>	✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

**Minor** Front Direction indicator insecure both mirror indicator casing missing (4.4.1 (c) (i))

**Advice** Oil leak but not excessive

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Under vehicle corrosion and components

**MOT #13**

2020-01-28 17:23

**MOT test number**

289624004942

**Result****✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Fail** Rear Exhaust has a major leak of exhaust gases back box (6.1.2 (a))
- Advice** Under vehicle corrosion and components
- Fail** Rear Suspension arm pin or bush excessively worn both (5.3.4 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Oil leak but not excessive
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
- Minor** Front Direction indicator insecure both mirror indicator casing missing (4.4.1 (c) (i))
- Advice** Offside Front headlight damaged slightly
- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #12**

2020-01-17 17:21

**MOT test number**

458471712957

**Result****✗ Failed**

- Advice** Central Rear High level not working
- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Offside Front Headlight damaged
- Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Rear Exhaust has a major leak of exhaust gases Back box (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Both front side reapers lens missing
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Pass with rectification** Nearside Front Side repeater not working (4.4.1 (a) (ii))
- Fail** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #11**

2019-01-14 15:49

**MOT test number**

141296499296

**Result****✓ Passed**

- Advice** Both front tyres bald on edges
- Advice** Axle swivel pins and bushes swivel pin and/or bush slightly worn Both rear trailing arm bushes (5.1.2 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Central Rear High level brake light not working

**MOT #10**

2017-06-20 10:56

**MOT test number**

629178814822

**Result**

✓ Passed

**Advice** Advise centre rear stop light inop**Advice** Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Advice** Advise front wipers worn**MOT #9**

2017-06-19 13:27

**MOT test number**

784029706179

**Result**

✗ Failed

**Advice** Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Advice** Advise front wipers worn**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Advise centre rear stop light inop**MOT #8**

2016-06-15 15:14

**MOT test number**

996504355149

**Result**

✓ Passed

**Advice** Centre stop light not working.**MOT #7**

2016-06-15 15:14

**MOT test number**

204899670405

**Result**

✗ Failed

**Pass with rectification** Rear Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Front Body has a sharp edge caused by damage Wing mirror. (6.1.C.1)**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Centre stop light not working.



<b>MOT #6</b>	2015-06-11 15:44
<b>MOT test number</b>	205802765465
<b>Result</b>	✓ Passed
<b>Notice</b>	Both front tyres worn on inner edge

<b>MOT #5</b>	2014-06-12 09:48
<b>MOT test number</b>	367023764161
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Brake pad(s) wearing thin (3.5.1g)
<b>Advice</b>	Nearside Front Brake pad(s) wearing thin (3.5.1g)
<b>Advice</b>	Nearside Rear Brake pad(s) wearing thin (3.5.1g)
<b>Advice</b>	Offside Front Brake pad(s) wearing thin (3.5.1g)

<b>MOT #4</b>	2013-06-13 14:37
<b>MOT test number</b>	949654563179
<b>Result</b>	✓ Passed
<b>Notice</b>	Bonnet opens by temporary means
<b>Advice</b>	Front Brake pad(s) wearing thin (3.5.1g)
<b>Advice</b>	Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b>	Nearside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #3** 2012-05-05 14:25**MOT test number** 168436422196**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Rear trailing arms bushes split**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test**Notice** Emissions too clean to detect**MOT #2** 2012-05-05 14:25**MOT test number** 549356022145**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Pass with rectification** Offside Headlamp aim too low (1.8)**Notice** Rear trailing arms bushes split**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test**Pass with rectification** Nearside Headlamp aim too far to the left (1.8)**Notice** Emissions too clean to detect**MOT #1** 2011-05-06 14:46**MOT test number** 209406921489**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-03-29
Current registration	*****
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-05-06
Last registration	2022-03-10
Complete history	<a href="#">See info</a>



Registration #1	2008-05-06	24 mi
Registration #2	2011-05-06	36.054 mi
Registration #3	2012-05-05	50.702 mi
Registration #4	2013-06-13	65.424 mi
Registration #5	2014-06-12	82.826 mi
Registration #6	2015-06-11	103.104 mi
Registration #7	2016-06-15	118.086 mi
Registration #8	2016-06-15	118.086 mi
Registration #9	2017-06-19	130.779 mi
Registration #10	2018-06-19	143.471 mi
Registration #11	2019-06-19	156.163 mi
Registration #12	2020-06-19	168.855 mi
Registration #13	2021-06-19	181.547 mi
Registration #14	2022-03-10	194.239 mi
Registration #15	2022-03-10	194.239 mi
Registration #16	2022-03-10	194.239 mi
Registration #17	2022-03-10	194.239 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	8R41969