





report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD I-DTEC ES GT
Colour	Grey
Year of manufacture	2014
Top speed	132 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	64.2 mpg
Consumption combined	53.3 mpg
CO2 emission	138 g/km
CO2 label	E



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-11-24

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

EY14DPZ report date: 2024-03-29

MOT expiry date	2025-02-28
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	18
Total items failed	0

MOT #12	2024-02-29 16:25
MOT test number	713319352770
Result	✓ Passed
Next expiry date	2025-02-28

MOT #11	2023-02-20 11:42
MOT test number	941993809082
Result	√ Passed
Advice Engine cover fitted	

MOT #10	2022-02-22 09:56
MOT test number	739443265218
Result	✓ Passed

nesan		V i assea
MOT #9		2022-02-21 11:27
MOT test number	er	125709000123
Result		× Failed
DANGEROUS	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
DANGEROUS (5.2.3 (d) (ii))	Nearside Front Tyre has a bulge, caused by separation or partial fail	ure of its structure

CarCheck.co.uk page 3/12



MOT #8 2021-02-02 14:37

MOT test number 294319285296

Result ✓ Passed

Advice Engine cover and undertrays fitted obscuring view

MOT #7 2021-01-26 17:13

MOT test number 351501172162

Result × Failed

MAJOR Nearside Front Side repeater not working Wing mirror repeater inoperative and covered up with tape (4.4.1 (a) (ii))

Advice Engine cover and undertrays fitted obscuring view

MOT #6 2020-01-30 09:22

MOT test number 874970629051

Result
✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2020-01-27 10:02

MOT test number 594106086728

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Brake fluid close to minimum mark (1.1.10 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

DANGEROUS Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



EY14DPZ

report date: 2024-03-29

MOT #4 2019-01-25 16:17

MOT test number 209834401089

Result ✓ Passed

Advice P

Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

MOT #3 2019-01-24 10:27

MOT test number 508540861258

Result X Failed

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm 225/50/17 (5.2.3 (e))

MOT #2 2018-02-02 17:15

MOT test number 734862111074

Result ✓ Passed

MOT #1 2017-03-01 11:34

MOT test number 731555655411

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	28 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Tyne	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

· ·		
For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full research		Α

	More info	>
Plate changes		
See in this check if this HONDA had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-03-14
Last registration	2024-02-29
Complete history	See info



Registration #1	2014-03-14	21 mi
Registration #2	2017-03-01	27.929 mi
Registration #3	2018-02-02	41.543 mi
Registration #4	2019-01-24	52.910 mi
Registration #5	2019-01-25	52.956 mi
Registration #6	2020-01-27	65.781 mi
Registration #7	2020-01-30	65.886 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4725 mm
Wheel base	2705 mm
Kerb weight	1632 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	N22B13503950

CarCheck.co.uk page 12/12