



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	VECTRA SRI NAV CDTI (150)
Colour	Green
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-02-03
Pictures	9
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2022-05-31
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	35
Total items failed	10

MOT #17 2021-06-01 13:37

MOT test number 942905410916

Result ✓ Passed

Next expiry date 2022-05-31

**Advice** Rear Brake pipe corroded, covered in grease or other material To hoses on both sides corroded (1.1.11 (c))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Rear Coil spring corroded Corroded on both sides (5.3.1 (b) (i))

**Advice** Bulb warning light on all bulbs working

**Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement Mounting stiff in operation (5.3.4 (a) (i))

**MOT #16**

2021-05-21 09:42

**MOT test number**

945627051830

**Result****✗ Failed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement Mounting stiff in operation (5.3.4 (a) (i))
- Advice** Bulb warning light on all bulbs working
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm Casing showing inner wall to tread area (5.2.3 (e))
- Advice** Rear Brake pipe corroded, covered in grease or other material To hoses on both sides corroded (1.1.11 (c))
- Fail** Exhaust system insecure Central and Rear ( sub frame) mountings rotted off exhaust pipe (6.1.2 (a))
- Advice** Rear Coil spring corroded Corroded on both sides (5.3.1 (b) (i))

**MOT #15**

2020-05-28 08:58

**MOT test number**

415668153867

**Result****✓ Passed**

- Advice** Front Registration plate deteriorated but not likely to be misread Damaged (0.1 (b))
- Advice** Offside Front Service brake binding but not excessively Requires attention (1.2.1 (f))
- Advice** Nearside Steering rack boot twisted
- Advice** Rear Coil spring corroded Corroded on both sides (5.3.1 (b) (i))
- Advice** Plastic under trays fitted obscuring some components
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))

**MOT #14**

2019-11-15 16:39

**MOT test number**

541116444934

**Result****✗ Failed**

- Advice** Front Macpherson strut corroded but not seriously weakened Corroded by spring cups on both sides (5.3.3 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tyre worn on inner edge (5.2.3 (e))
- Advice** Rear Exhaust mounting defective Rotted off pipe by sub frame (6.1.2 (a))
- Minor** Offside Obligatory mirror slightly damaged Glass damaged (3.3 (b) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Shock absorbers light misting of oil or has limited damping effect On both sides (5.3.2 (b))
- Fail** Brake performance not tested Due to condition of brake pipes (1.2.1 (g))
- Advice** Rear Coil spring corroded Corroded on both sides (5.3.1 (b) (i))
- Fail** Offside Rear Brake pipe at imminent risk of failure or fracture Corroded by fuel tank (front to rear) (1.1.11 (a))
- Fail** Front Suspension component ball joint excessively worn On both sides (5.3.4 (a) (i))

**MOT #13**

2018-11-19 16:26

**MOT test number**

967376350174

**Result****✓ Passed**

- Advice** Rear All direction indicators slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2018-01-12 15:11

**MOT test number**

210505965984

**Result****✓ Passed**

**MOT #11** 2017-01-27 14:51**MOT test number** 793770286447**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #10** 2016-01-21 09:53**MOT test number** 298276871400**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front tyre worn hard on edges**MOT #9** 2016-01-20 15:42**MOT test number** 449974285839**Result** ✗ Failed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front tyre worn hard on edges**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #8** 2015-01-23 16:11**MOT test number** 105823625084**Result** ✓ Passed**MOT #7** 2015-01-23 16:11**MOT test number** 158123925440**Result** ✗ Failed**Pass with rectification** Rear Direction indicators incorrect colour (1.4.A.2f)

**MOT #6** 2014-01-13 12:11**MOT test number** 188593014483**Result** ✓ Passed**MOT #5** 2013-01-28 14:34**MOT test number** 675998823098**Result** ✓ Passed**Notice** Flat spot on N/S/F tyre inner edge**MOT #4** 2012-01-16 10:20**MOT test number** 226636712094**Result** ✓ Passed**MOT #3** 2011-01-12 15:23**MOT test number** 849892011048**Result** ✓ Passed**Notice** Nearside rear brake disk slightly pitted and scored**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Direction indicators slightly discoloured (1.4.A.2f)**MOT #2** 2010-02-01 08:43**MOT test number** 734702430097**Result** ✓ Passed**MOT #1** 2010-01-29 15:31**MOT test number** 233499120029**Result** ✗ Failed**Advice** Rear brake disc slightly scored (3.5.1h)**Fail** Offside Rear coil spring incomplete (2.4.C.1a)



Tax & MOT check

X

Untaxed

Tax expired:  
30 June 2022

X

MOT

Expired:  
31 May 2022

Tax status	Expired at 30 June 2022
Days left	670 days too late
MOT expiry date	31 May 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 KY07FGM
Plate since	2019-06-29
Current registration	 KY07FGM
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-03-19
Last registration	2021-06-01
Complete history	<a href="#">See info</a>



Registration #1	2007-03-19	19 mi
Registration #2	2010-01-29	58.191 mi
Registration #3	2010-02-01	58.191 mi
Registration #4	2011-01-12	77.055 mi
Registration #5	2012-01-16	95.021 mi
Registration #6	2013-01-28	109.119 mi
Registration #7	2014-01-13	114.573 mi
Registration #8	2015-01-23	121.773 mi
Registration #9	2016-01-20	127.641 mi
Registration #10	2016-01-20	127.641 mi
Registration #11	2016-01-20	127.641 mi
Registration #12	2016-01-20	127.641 mi
Registration #13	2016-01-20	127.641 mi
Registration #14	2016-01-20	127.641 mi
Registration #15	2016-01-20	127.641 mi
Registration #16	2016-01-20	127.641 mi
Registration #17	2016-01-20	127.641 mi
Registration #18	2016-01-20	127.641 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1798 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1456 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	17224973