



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D DRIVE SE
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2022-01-17
Pictures	29
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-05
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	17
Total items failed	5

MOT #15 2024-02-06 13:30

MOT test number 380382554767

Result ✓ Passed

Next expiry date 2025-02-05

Advice Engine covers and under trays fitted obscuring some components

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2024-02-01 10:40

MOT test number 229238396723

Result ✗ Failed

Fail Nearside Obligatory mirror does not provide a view to the rear (3.3 (c))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Engine covers and under trays fitted obscuring some components

MOT #13 2023-01-30 10:26

MOT test number 457971178270

Result ✓ Passed

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Engine covers and undertrays fitted obscuring some components

**MOT #12** 2023-01-25 12:20**MOT test number** 145662303143**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Engine covers and undertrays fitted obscuring some components**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #11** 2022-01-24 16:08**MOT test number** 299937335079**Result** ✓ Passed**MOT #10** 2021-05-06 13:32**MOT test number** 921376440057**Result** ✓ Passed**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #9** 2020-05-13 09:53**MOT test number** 735664516157**Result** ✓ Passed**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #8** 2020-05-13 09:53**MOT test number** 792364762855**Result** ✗ Failed**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #7** 2019-02-19 11:01**MOT test number** 620442949163**Result** ✓ Passed**MOT #6** 2018-02-17 12:15**MOT test number** 905148953644**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2017-02-21 12:59**MOT test number** 757667803056**Result** ✓ Passed**Advice** Undertrays fitted**Advice** Nearside Rear tyre worn**MOT #4** 2016-03-04 16:56**MOT test number** 824480716712**Result** ✓ Passed



MOT #3	2015-06-19 08:28
MOT test number	536550275136
Result	✓ Passed
MOT #2	2014-06-10 08:33
MOT test number	835711964163
Result	✓ Passed
MOT #1	2013-06-26 13:23
MOT test number	888037173144
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
5 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	5 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-06-28
Last registration	2024-02-06
Complete history	See info



Registration #1	2010-06-28	20 mi
Registration #2	2013-06-26	29.320 mi
Registration #3	2014-06-10	35.117 mi
Registration #4	2015-06-19	12.586 mi
Registration #5	2016-03-04	45.630 mi
Registration #6	2017-02-21	56.042 mi
Registration #7	2018-02-17	66.638 mi
Registration #8	2019-02-19	74.754 mi
Registration #9	2020-05-13	82.091 mi
Registration #10	2020-05-13	82.091 mi
Registration #11	2020-05-13	82.091 mi
Registration #12	2020-05-13	82.091 mi
Registration #13	2020-05-13	82.091 mi
Registration #14	2020-05-13	82.091 mi
Registration #15	2020-05-13	82.091 mi
Registration #16	2020-05-13	82.091 mi
Registration #17	2020-05-13	82.091 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1382 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	957548