



General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI DSG 140
Colour	Blue
Year of manufacture	2009
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-08-30
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2024-03-17
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	35
Total items failed	8

MOT #15 2023-03-18 13:00**MOT test number** 900295062401**Result** Passed**Next expiry date** 2024-03-17

- Advice** Items removed from driver's view prior to test
- Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Passenger seat(s) missing at time of test
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2022-02-24 10:17**MOT test number** 221983108770**Result** Passed

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Rear Seat belt buckle slightly damaged (7.1.2 (d))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13**

2021-02-16 17:12

MOT test number

924588225009

Result

✓ Passed

Advice Nearside Front wing mirror damaged**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front fog lamp lens damaged**MOT #12**

2020-02-20 17:25

MOT test number

758012204821

Result

✓ Passed

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush on both arms (5.3.4 (a) (i))**Advice** Central Rear Seat belt buckle slightly damaged casing missing (7.1.2 (d))**Advice** Engine covers and under trays fitted not allowing full inspection**Minor** Nearside Front Brake hose slightly twisted (1.1.12 (b) (i))**MOT #11**

2019-02-19 16:56

MOT test number

803205812618

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2019-02-19 09:30

MOT test number

655238476688

Result**✗ Failed****Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #9**

2018-02-26 16:09

MOT test number

808606592550

Result**✓ Passed****Advice** Central Rear Seat belt attachment fitting slightly deteriorated plastic casing missing (5.2.3)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #8**

2018-02-26 14:04

MOT test number

885872001410

Result**✗ Failed****Advice** Central Rear Seat belt attachment fitting slightly deteriorated plastic casing missing (5.2.3)**Advice** Nearside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Nearside Rear Nail in tyre**Fail** Nearside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #7** 2017-03-02 09:15**MOT test number** 443910247925**Result** ✓ Passed**Advice** Nearside Non obligatory mirror damaged**Advice** Nearside Side repeater obscured but not more than 50% (1.4.A.2d)**MOT #6** 2016-02-08 14:31**MOT test number** 895175964563**Result** ✓ Passed**MOT #5** 2015-06-10 15:01**MOT test number** 615231765129**Result** ✓ Passed**MOT #4** 2014-06-12 13:02**MOT test number** 205193464103**Result** ✓ Passed**Notice** OSR Tyre perishing**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2013-06-17 13:28**MOT test number** 815788963148**Result** ✓ Passed**Notice** Offside side repeater damaged**Notice** Front tyres worn to 3mm



MOT #2	2013-06-17 11:09
MOT test number	918848163150
Result	✗ Failed
Notice	Offside side repeater damaged
Pass with rectification	Nearside Headlamp aim too low (1.8)
Fail	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
Notice	Front tyres worn to 3mm
Pass with rectification	Offside Headlamp aim too low (1.8)

MOT #1	2012-07-05 12:10
MOT test number	795087982140
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✗
MOT

Expired:
17 March 2024

Tax status	Valid until 1 May
Days left	3
MOT expiry date	17 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 RJ09JNO
Plate since	2024-03-29
Current registration	 RJ09JNO
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-07-02
Last registration	2023-03-18
Complete history	See info



Registration #1	2009-07-02	22 mi
Registration #2	2012-07-05	19.592 mi
Registration #3	2013-06-17	23.756 mi
Registration #4	2013-06-17	23.756 mi
Registration #5	2014-06-12	28.461 mi
Registration #6	2015-06-10	35.588 mi
Registration #7	2016-02-08	38.256 mi
Registration #8	2017-03-02	68.217 mi
Registration #9	2018-02-26	101.235 mi
Registration #10	2019-03-20	131.217 mi
Registration #11	2019-03-20	131.217 mi
Registration #12	2019-03-20	131.217 mi
Registration #13	2019-03-20	131.217 mi
Registration #14	2019-03-20	131.217 mi
Registration #15	2019-03-20	131.217 mi
Registration #16	2019-03-20	131.217 mi
Registration #17	2019-03-20	131.217 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Max. allowed weight	2290 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

BKD C66894