



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	Blue
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-02-14
Pictures	8
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-29
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	17
Total items failed	3

MOT #15 2023-11-22 15:03**MOT test number** 222870636783**Result** Passed**Next expiry date** 2024-11-29

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #14 2023-11-21 12:47**MOT test number** 829509416174**Result** Failed

DANGEROUS Nearside Rear Anti-roll bar linkage fractured partially missing (5.3.3 (b) (ii))

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #13 2022-11-24 16:31**MOT test number** 942028751482**Result** Passed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12** 2021-11-26 10:45**MOT test number** 501360084201**Result** ✓ Passed**Advice** Offside Rear Direction Indicator slightly discoloured (4.4.3 (a))**MOT #11** 2020-11-30 16:27**MOT test number** 288883921854**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10** 2020-11-27 13:25**MOT test number** 499666903534**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9** 2019-06-04 13:06**MOT test number** 741363748683**Result** ✓ Passed**MOT #8** 2018-05-22 15:03**MOT test number** 751400867561**Result** ✓ Passed**MOT #7** 2017-10-26 08:31**MOT test number** 331921053032**Result** ✓ Passed

**MOT #6** 2017-10-26 08:31**MOT test number** 827068280117**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #5** 2016-05-17 12:19**MOT test number** 425958585061**Result** ✓ Passed**MOT #4** 2015-04-28 12:36**MOT test number** 715958215173**Result** ✓ Passed**MOT #3** 2014-05-08 11:53**MOT test number** 377668724103**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-05-08 11:53**MOT test number** 529178424169**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #12013-05-01 15:35

MOT test number938481623169

Result

✓ Passed

NoticeEngine covers fitted obscuring some components in the engine bay

NoticeUnder-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
29 November 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	29 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-05-14
Last registration	2023-11-22
Complete history	See info



Registration #1	2010-05-14	13 mi
Registration #2	2013-05-01	22.769 mi
Registration #3	2014-05-08	28.468 mi
Registration #4	2015-04-28	31.831 mi
Registration #5	2016-05-17	36.119 mi
Registration #6	2017-10-26	45.232 mi
Registration #7	2017-10-26	45.232 mi
Registration #8	2018-05-22	50.181 mi
Registration #9	2019-05-22	55.130 mi
Registration #10	2019-05-22	55.130 mi
Registration #11	2019-05-22	55.130 mi
Registration #12	2019-05-22	55.130 mi
Registration #13	2019-05-22	55.130 mi
Registration #14	2019-05-22	55.130 mi
Registration #15	2019-05-22	55.130 mi
Registration #16	2019-05-22	55.130 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1299 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	181935