





report date: 2024-03-29

General information

Make	RENAULT
Model	GRAND SCENIC GRAND DYNAMIQUE TOMTOM DCI FAP
Colour	Bronze
Year of manufacture	2011
Top speed	112 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/14



Internet history

Entry	1

Lifety 1	
Date	2021-12-31
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2025-03-04
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	35
Total items failed	11

MOT #14		2024-03-05 12:28
MOT test	number	956920352607
Result		✓ Passed
Next exp	iry date	2025-03-04
Advice	Rear Brake roughness	
Advice	Rear Direction indicator slightly discoloured Both sides (4.4.3 (a))	
Advice	Nearside Rear Nail in tyre Unrepairable	
Minor	Nearside Obligatory mirror slightly loose (3.3 (b) (i))	
Advice	Brake pedal wearing smooth (1.1.2 (c))	
Advice	Rear Disc corroded	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Driver's door hinge deteriorated but the door can still be readily opened and	closed (6.2.3 (c) (i))

CarCheck.co.uk page 3/14



MOT #13 2024-03-04 11:46

MOT test number 232876911656

Result X Failed

Advice Brake pedal wearing smooth (1.1.2 (c))

Fail Reversing lamp inoperative (4.6.1 (a))

Minor Nearside Obligatory mirror slightly loose (3.3 (b) (i))

Advice Rear Direction indicator slightly discoloured Both sides (4.4.3 (a))

Advice Rear Disc corroded

Fail Offside Rear Inner Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Nearside Rear Nail in tyre Unrepairable

Fail Rear fog lamp not working (4.5.1 (a) (ii))

Advice Driver's door hinge deteriorated but the door can still be readily opened and closed (6.2.3 (c) (i))

Fail Nearside Headlamp aim too low (4.1.2 (a))

Advice Rear Brake roughness

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #12 2023-01-18 15:14

MOT test number 569690644304

Result \rightarrow Passed

Advice Offside Play in steering rack inner joint(s)

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2022-02-04 09:11

MOT test number 559159634630

CarCheck.co.uk page 4/14



MOT #10 2021-05-04 13:00

MOT test number 966496553254

MOT #9 2021-04-28 13:47

MOT test number 145816847066

Result X Failed

Advice Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Minor Offside Side repeater insecure lens missing (4.4.1 (c) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Fail Offside Rear Seat belt damaged Centre row (7.1.2 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #8 2020-05-26 11:41

MOT test number 594475547781

CarCheck.co.uk page 5/14



MOT #7

DU11WXX
report date: 2024-03-29

2019-04-06 08:34

MOT test number 237814092349

MOT #6 2018-04-11 11:46

MOT test number 199673544295

Result ✓ Passed

MOT #5 2017-04-13 14:01

MOT test number 463602729865

Result
✓ Passed

Advice No emissions printout due to low emissions

MOT #4 2016-03-26 11:36

MOT test number 904536055946

Result ✓ Passed

MOT #3 2015-03-23 11:00

MOT test number 747122385061

Result
✓ Passed

MOT #2 2014-03-20 16:39

MOT test number 198889074488

Result \(\sqrt{Passed} \)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Under-trays fitted obscuring some underside components


Notice Items removed from driver's view prior to test

CarCheck.co.uk page 6/14



DU11WXX

report date: 2024-03-29



CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	4 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

e when miscory	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-31
Last registration	2024-03-05
Complete history	See info



Registration #1	2011-03-31	17 mi
Registration #2	2014-03-19	35.857 mi
Registration #3	2014-03-20	35.857 mi
Registration #4	2015-03-23	43.797 mi
Registration #5	2016-03-26	52.889 mi
Registration #6	2017-04-13	62.673 mi
Registration #7	2018-04-11	72.189 mi
Registration #8	2019-04-06	81.835 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7070.70.70

More info >

77.777 86

CarCheck.co.uk page 13/14



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	76%
Pedestrian	42%
Safety systems	99%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1845 mm
Height	1672 mm
Length	4573 mm
Wheel base	2770 mm
Kerb weight	1430 kg
Max. allowed weight	2128 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles CarCheck.co.uk	2 page 14/1