





report date: 2024-03-29

## General information

Make	MERCEDES
Model	CLK CLK500 AVANTGARDE
Colour	Black
Year of manufacture	2006
Top speed	155 mph
0 - 60 mph	5.2 seconds
Gearbox	7 speed automatic

# Engine & fuel consumption

Power	383 BHP
Max. torque	530 Nm at 2.800 rpm
Engine capacity	5.462 cc
Cylinders	8
Fuel type	Petrol
Consumption city	8.3 mpg
Consumption extra urban	16.7 mpg
Consumption combined	11.4 mpg
CO2 emission	273 g/km
CO2 label	М



CarCheck.co.uk page 1/14



# Internet history

## Entry 1

Date 2021-09-14

Pictures 24

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-08-22
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	19
Total items failed	6

MOT #19	2023-08-23 14:27
MOT test number	377316203220
Result	✓ Passed
Next expiry date	2024-08-22
Advice Brake pipe corroded, covered in grease or other material all on vehicle (1.1.11 (	(c))

MOT #18	2022-06-13 15:27
MOT test number	874057117910
Result	<b>√</b> Passed

		•
MOT #	17	2022-06-07 13:26
MOT te	st number	842776370170
Result		<b>X</b> Failed
Fail	Offside Front Lower Suspension arm pin or bush excessively worn rear arm (5.3	3.4 (a) (i))
Fail	Nearside Front Lower Suspension arm pin or bush excessively worn rear arm (5	5.3.4 (a) (i))

MOT #16		2021-06-18 14:06
MOT test	number	412479214802
Result		✓ Passed
Advice	Rear Brake pipe corroded, covered in grease or other material Both, a	bove fuel tank (1.1.11 (c))

CarCheck.co.uk page 3/14



**MOT #15** 2020-09-14 15:23

**MOT test number** 581588079687

**MOT #14** 2019-09-17 13:55

MOT test number 674663494155

**Result** ✓ Passed

Advice Rear Brake pad(s) wearing thin over half worn (1.1.13 (a) (ii))

MOT #13 2019-09-17 13:55

**MOT test number** 854465280312

**Result** X Failed

**Advice** Rear Brake pad(s) wearing thin over half worn (1.1.13 (a) (ii))

**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #12 2018-09-18 14:13

**MOT test number** 261464948987

**Result** ✓ Passed

MOT #11 2017-09-28 16:28

**MOT test number** 853299892236

**Result** ✓ Passed

CarCheck.co.uk page 4/14



MOT #10 2016-09-08 17:05 **MOT test number** 604765620042 Result ✓ Passed **Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c) Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Drivers interior dash lower panel close to brake pedal Advice Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c) **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #9	2015-09-26 10:04
MOT test number	735000757299
Result	✓ Passed

MOT #8		2014-09-25 13:36
MOT test	number	359358264209
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	N/side rear metal brake pipe corroded ( near fuel tank )	
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A'	(8.3.1d)
Notice	N/side front wheel bearing very slight play in	
Notice	Nail in nearside rear tyre	
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)	
Notice	Both rear tyres on wear indicators (low tread)	

CarCheck.co.uk page 5/14



MOT #7 2013-09-10 14:17

**MOT test number** 777223353216

MOT #6 2013-09-10 13:30

**MOT test number** 638123453292

Result × Failed

Fail Front registration plate deteriorated (6.3.1d)

MOT #5 2012-09-26 14:15

**MOT test number** 247970772232

**Notice** Brake fluid low

MOT #4 2012-09-25 12:21

**MOT test number** 298449862295

Result × Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Notice** Brake fluid low

MOT #3 2011-09-15 11:12

**MOT test number** 938538351258

**MOT #2** 2010-09-09 11:00

**MOT test number** 662582050257

CarCheck.co.uk page 6/14



MOT #1 2009-09-15 12:28

**MOT test number** 423858159227

**Result** ✓ Passed

CarCheck.co.uk page 7/14



## Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	22 August 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 8/14



## Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date
Category
Type
Damage 2

Damage 2

Date

Category

**Type** 



#### Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



O	والمراجع والأجا
Owner	nistorv

Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	
*********	
***************************************	
**********	
Plate changes	More info >
See in this check if this MERCEDES had different number plates.	
Mumber of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

More info >

CarCheck.co.uk page 12/14



# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-09-25
Last registration	2023-08-23
Complete history	See info



Registration #1	2006-09-25	12 mi
Registration #2	2009-09-15	40.595 mi
Registration #3	2010-09-09	62.381 mi
Registration #4	2011-09-15	84.083 mi
Registration #5	2012-09-25	94.319 mi
Registration #6	2012-09-26	94.319 mi
Registration #7	2013-09-10	99.004 mi
Registration #8	2013-09-10	99.004 mi
Registration #9	2014-09-25	105.486 mi
Registration #10	2015-09-26	109.958 mi
Registration #11	2016-09-08	115.763 mi
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		77.777 46

More info >

CarCheck.co.uk page 13/14



# Dimensions & weight

Width	1740 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Max. allowed weight	2130 kg

# Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Engine number	27396730071627

CarCheck.co.uk page 14/14