





report date: 2024-03-28

General information

Make	DACIA	
Model	LOGAN STEPWAY COMFORT TCE	
Colour	White	
Year of manufacture	2018	
Top speed	106 mph	
0 - 60 mph	12.4 seconds	
Gearbox	5 speed Manual	

Engine & fuel consumption

Power	90 BHP
Max. torque	140 Nm at 2.250 rpm
Engine capacity	898 cc
Cylinders	3
Fuel type	Petrol
Consumption city	43.5 mpg
Consumption extra urban	57.6 mpg
Consumption combined	2.8 mpg
CO2 emission	125 g/km
CO2 label	D



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2021-09-21

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-09-21	
------	------------	--

Pictures 2

Listing price <u>View report</u>





source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-10-18
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #4	2023-10-19 10:14
MOT test number	615061535167
Result	✓ Passed
Next expiry date	2024-10-18
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

		2023-10-19 10:14
number		868839089540
		× Failed
Nearside Front T	yre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
th rectification	Nearside Front Headlamp not working on dipped beam (4.1.	1 (a) (ii))
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
	Offside Rear Tyr	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) th rectification Nearside Front Headlamp not working on dipped beam (4.1.1) Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 3/11



MOT #2 2022-10-15 10:09

MOT test number 599542521394

Result ✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1 2021-10-05 10:01

MOT test number 457051640460

Result

Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	18 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this DACIA. See if, where and when this DACIA had damage and the car repair costs. We also check if this DACIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra DACIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this DACIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



FV68FVT

report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this DACIA? How many owners Check it in the premium report and see all owner registrations. Download the full report	

Plate changes	More info >
See in this check if this DACIA had different number plates.	
Number of plates	
Correct registration	IK SIN
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this DACIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this DACIA has been settled.

If not, and you buy this DACIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this DACIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-12-14
Last registration	2023-10-19
Complete history	See info



Registration #1	2018-12-14	19 mi
Registration #2		11.777 es
Registration #3		11.777 es
Registration #4	2021-10-05	24.282 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11,177 es

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1590 mm
Length	4528 mm
Wheel base	2635 mm
Kerb weight	1090 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	D625356

CarCheck.co.uk page 11/11