




report date: 2024-03-28

General information

| | |
|---------------------|--------------------------|
| Make | VAUXHALL |
| Model | ANTARA EXCLUSIV CDTI S/S |
| Colour | Grey |
| Year of manufacture | 2014 |
| Top speed | 117 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 161 BHP |
| Max. torque | 350 Nm at 2.000 rpm |
| Engine capacity | 2.231 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.7 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 46.3 mpg |
| CO2 emission | 160 g/km |
| CO2 label | G |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-06 |
| Pictures | 1 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-08-10 |
| MOT pass rate | 67 % |
| MOT passed | 8 |
| Failed MOT tests | 4 |
| Total advice items | 31 |
| Total items failed | 9 |

| | |
|------------------|---|
| MOT #12 | 2023-08-10 10:05 |
| MOT test number | 491933438660 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-10 |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Offside Rear Brake pipe corroded, covered in grease or other material front to rear by sub-frame/fuel tank (1.1.11 (c)) |
| Minor | Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

**MOT #11**

2023-08-08 10:05

MOT test number

311409277228

Result

✗ Failed

- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Headlamp aim too low (4.1.2 (a))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect no image (4.1.2 (c))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material front to rear by sub-frame/fuel tank (1.1.11 (c))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #10

2022-08-03 10:15

MOT test number

373512145896

Result

✓ Passed

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9

2022-08-03 09:08

MOT test number

227714077704

Result

✗ Failed

- Fail** Rear Reversing lamp inoperative (4.6.1 (a))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8

2021-08-11 10:00

MOT test number

664568045174

Result

✓ Passed



| | |
|-----------------|--|
| MOT #7 | 2021-08-10 10:36 |
| MOT test number | 324905551525 |
| Result | ✗ Failed |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) |
| Fail | Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |
| Fail | Nearside Front Position lamp not working (4.2.1 (a) (ii)) |
| Advice | Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) |

| | |
|-----------------|--|
| MOT #6 | 2021-02-23 11:06 |
| MOT test number | 589612579185 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |

**MOT #5** 2021-02-23 11:06**MOT test number** 119605314037**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #4** 2020-02-22 12:22**MOT test number** 310601310160**Result** ✓ Passed**MOT #3** 2019-02-22 10:37**MOT test number** 638697380923**Result** ✓ Passed**MOT #2** 2018-01-20 09:51**MOT test number** 496967333226**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



| | |
|-----------------|--|
| MOT #1 | 2017-01-21 09:18 |
| MOT test number | 149315722309 |
| Result | ✓ Passed |
| Advice | Child Seat fitted not allowing full inspection of adult belt |



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
10 August 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 95 |
| MOT expiry date | 10 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | NG63SZP |
| Plate since | 2019-09-29 |
| Current registration | NG63SZP |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2014-01-31 |
| Last registration | 2023-08-10 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2014-01-31 | 16 mi |
| Registration #2 | 2017-01-21 | 17.607 mi |
| Registration #3 | 2018-01-20 | 26.997 mi |
| Registration #4 | 2019-02-22 | 37.002 mi |
| Registration #5 | 2020-02-22 | 45.364 mi |
| Registration #6 | 2021-02-23 | 51.828 mi |
| Registration #7 | 2021-02-23 | 51.828 mi |
| Registration #8 | 2022-02-22 | 51.828 mi |
| Registration #9 | 2022-02-22 | 51.828 mi |
| Registration #10 | 2022-02-22 | 51.828 mi |
| Registration #11 | 2022-02-22 | 51.828 mi |
| Registration #12 | 2022-02-22 | 51.828 mi |
| Registration #13 | 2022-02-22 | 51.828 mi |
| Registration #14 | 2023-08-10 | 51.828 mi |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 95% |
| Children | 84% |
| Pedestrian | 46% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2085 mm |
| Height | 1761 mm |
| Length | 4596 mm |
| Wheel base | 2707 mm |
| Kerb weight | 1836 kg |
| Max. allowed weight | 2505 kg |

Additional information

| | |
|-----------------|-------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | Z22D1 294843K LNQ |