



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA DESIGN
Colour	Silver
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	131 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-08-26
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-11-01
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	13
Total items failed	0

MOT #13	2023-10-26 09:45
MOT test number	593996090400
Result	✓ Passed
Next expiry date	2024-11-01
Advice	Nearside Front Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #12	2022-10-29 08:56
MOT test number	149136673835
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Central Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #11	2021-11-02 16:12
MOT test number	216840550830
Result	✓ Passed

MOT #10	2020-09-09 10:31
MOT test number	546192779811
Result	✓ Passed

**MOT #9** 2019-08-29 15:34**MOT test number** 766948415077**Result** ✓ Passed**Advice** Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #8** 2019-08-29 11:35**MOT test number** 558085541805**Result** ✗ Failed**MAJOR** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #7** 2018-09-18 14:24**MOT test number** 282178075035**Result** ✓ Passed**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #6** 2017-09-19 10:10**MOT test number** 309179095508**Result** ✓ Passed



<b>MOT #5</b>	2016-09-09 10:12
<b>MOT test number</b>	523144291809
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2015-09-25 13:52
<b>MOT test number</b>	895555094529
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2014-02-12 10:47
<b>MOT test number</b>	925923144054
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2013-02-27 09:29
<b>MOT test number</b>	957468653009
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2012-02-23 10:53
<b>MOT test number</b>	126414552019
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
1 November 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	1 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>LX09TKO</b>
Plate since	2019-03-28
Current registration	<b>LX09TKO</b>
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-03-09
Last registration	2023-10-26
Complete history	<a href="#">See info</a>



Registration #1	2009-03-09	19 mi
Registration #2	2012-02-23	24.544 mi
Registration #3	2013-02-27	26.566 mi
Registration #4	2014-02-12	29.659 mi
Registration #5	2015-09-25	35.417 mi
Registration #6	2016-09-09	39.014 mi
Registration #7	2017-09-19	42.407 mi
Registration #8	2018-09-18	45.133 mi
Registration #9	2019-09-26	55.377 mi
Registration #10	2019-09-26	55.377 mi
Registration #11	2019-09-26	55.377 mi
Registration #12	2019-09-26	55.377 mi
Registration #13	2019-09-26	55.377 mi
Registration #14	2019-09-26	55.377 mi
Registration #15	2019-09-26	55.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1096095