





report date: 2024-03-28

General information

Make	ТОҮОТА
Model	COROLLA VVTI T SPIRIT
Colour	Silver
Year of manufacture	2006
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.8 mpg
Consumption combined	40.3 mpg
CO2 emission	168 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date	2022-02-07

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2022-02-06
Pictures	3

Listing price <u>View report</u>







source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2023-01-18
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	11
Total items failed	5

MOT #17	2022-01-19 11:50
MOT test number	396989199586
Result	✓ Passed
Next expiry date	2023-01-18
Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))	

MOT #16		2020-10-09 13:54
MOT test	number	470881963804
Result		✓ Passed
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))	
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))	

MOT #15		2019-10-09 14:35
MOT test	number	776480949459
Result		✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #14 2019-10-09 09:24 **MOT** test number 892961623468 Result × Failed Fail Front Brakes imbalanced across an axle by more than 50% Axle 1 (1.2.1 (b) (ii)) **Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Fail** Nearside Front Service brake excessively binding (1.2.1 (f)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Fail**

MOT test number

Fesult

Minor

Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Minor

Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice

Brake pipe corroded, covered in grease or other material (1.1.11 (c))

 MOT #12
 2017-10-06 08:34

 MOT test number
 586964315443

 Result
 ✓ Passed

 MOT #11
 2017-10-06 08:34

 MOT test number
 102443315733

 Result
 X Failed

 Pass with rectification
 Nearside Headlamp aim too low (1.8)

MOT #10	2016-10-27 11:06
MOT test number	327099044547
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #9		2016-10-27 11:05
MOT test number		386757499356
Result		X Failed
Pass with rectification	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #8	2015-10-26 11:16
MOT test number	785714059099
Result	✓ Passed
MOT #7	2014-10-24 16:07
MOT test number	137297294255
Result	✓ Passed
MOT #6	2013-10-23 11:44
MOT test number	307066493220
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Nearside Front Tyre worn close to the legal lillit (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2012-10-06 10:41
MOT test number	708860982288
Result	✓ Passed
MOT #4	2011-11-02 14:39
MOT test number	568956701319
Result	✓ Passed
MOT #3	2011-05-20 10:22
MOT test number	288960441192
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

 MOT #2
 2010-05-20 11:46

 MOT test number
 734070540194

 Result
 ✓ Passed

 MOT #1
 2009-05-22 10:41

 MOT test number
 291002449139

 Result
 ✓ Passed

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-06-19
Last registration	2022-01-19
Complete history	See info



Registration #1	2006-06-19	6 mi
Registration #2	2009-05-22	24.077 mi
Registration #3	2010-05-20	30.929 mi
Registration #4	2011-05-20	37.545 mi
Registration #5	2011-11-02	37.833 mi
Registration #6	2012-10-06	44.245 mi
Registration #7	2013-10-23	48.777 mi
Registration #8	2014-10-24	54.642 mi
Registration #9	2015-10-26	59.603 mi
Registration #10	2016-10-27	65.316 mi
Registration #11		9.70 es
Registration #12		71.777 es
Registration #13		9.70 es
Registration #14		71.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		19.700 esi
Registration #18		11.777 es
Registration #19		D.707 es
Registration #20		11.777 au

More info >

CarCheck.co.uk page 11/12



GP06WLD report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1220 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/1

Number of axles 2

Engine number 3ZZU778649