



A065TZU


report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO SE
Colour	Red
Year of manufacture	2015
Top speed	100 mph
0 - 100 km/h	14.3 seconds
0 - 60 mph	15.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	44 kW / 60 HP / 59 BHP
Max. torque	95 Nm at 3.000 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	106 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-10-02
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-09
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	9
Total items failed	2

MOT #6	2023-06-01 15:11
MOT test number	558024938976
Result	✓ Passed
Next expiry date	2024-06-09
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5	2022-06-10 16:48
MOT test number	144809856591
Result	✓ Passed
Advice	Offside Front Service brake fluctuating, but not excessively disc worn corroded - high imbalance (1.2.1 (e))
Advice	Rear Inner Tyre slightly damaged/cracking or perishing slight (5.2.3 (d) (ii))

MOT #4	2022-06-10 16:48
MOT test number	439540556197
Result	✗ Failed
Advice	Offside Front Service brake fluctuating, but not excessively disc worn corroded - high imbalance (1.2.1 (e))
Advice	Rear Inner Tyre slightly damaged/cracking or perishing slight (5.2.3 (d) (ii))
Pass with rectification	Supplementary restraint system warning lamp indicates a fault code read cleared reset - no light on (7.1.6 (a))
Pass with rectification	Windscreen wiper does not clear the windscreen effectively all worn slight - supplied by customer worn slight (3.4 (b) (ii))

**MOT #3** 2020-10-20 09:43**MOT test number** 388041144702**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracked and perished in tread (5.2.3 (d) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened pitted on surface area (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracked in tread (5.2.3 (d) (ii))**MOT #2** 2019-10-28 10:43**MOT test number** 626836594416**Result** ✓ Passed**MOT #1** 2018-10-29 17:03**MOT test number** 345745271745**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
9 June 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	9 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2015-11-30
Last registration	2023-06-01
Complete history	See info



Registration #1	2015-11-30	27 mi
Registration #2	2018-10-29	8.030 mi
Registration #3	2019-10-28	17.163 mi
Registration #4	2020-10-20	23.552 mi
Registration #5	2021-10-20	25.277 mi
Registration #6	2022-10-20	25.277 mi
Registration #7	2023-06-01	25.277 mi
Registration #8	2023-06-01	25.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1453 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1067 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CHYA451626