



EK090DG

report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT CONNECT T220 LR DCB
Colour	White
Year of manufacture	2009
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-06
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-09-13
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	21
Total items failed	18

MOT #16	2021-09-09 08:16
MOT test number	291850742644
Result	✓ Passed
Next expiry date	2022-09-13
Advice	Nearside Play in steering rack inner joint(s)

MOT #15	2020-09-14 07:15
MOT test number	366785840610
Result	✓ Passed

MOT #14	2020-09-11 09:03
MOT test number	425099280340
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #13	2019-06-17 09:25
MOT test number	602521513399
Result	✓ Passed



MOT #12	2018-06-19 14:03
MOT test number	115041100371
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2018-06-19 08:43
MOT test number	911605394440
Result	✗ Failed
Fail	Offside Front Brake pipe excessively corroded to rear (1.1.11 (c))
Fail	Offside Front Position lamp not working (4.2.1 (a))
Fail	Rear Stop lamp(s) not working high level (4.3.1 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Brake pipe excessively corroded to rear (1.1.11 (c))
Fail	Front Exhaust has a major leak of exhaust gases to rear (6.1.2 (a))
Fail	Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #10	2017-06-08 14:07
MOT test number	545355927427
Result	✓ Passed

MOT #9	2017-06-07 09:08
MOT test number	148480596946
Result	✗ Failed
Fail	Offside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
Fail	Fuel cap/sealing device mounting flange/sealing method defective (7.2.4c)
Fail	Exhaust emits an excessive level of metered smoke (7.4.B.3a)

**MOT #8** 2016-05-20 08:10**MOT test number** 371046682650**Result** ✓ Passed**Advice** Offside Rear tyre has a nail in tread**Advice** Offside Rear tyre worn on inner edge**MOT #7** 2016-05-20 08:10**MOT test number** 235682656702**Result** ✗ Failed**Pass with rectification** Battery insecure (1.9.1)**Advice** Offside Rear tyre worn on inner edge**Advice** Offside Rear tyre has a nail in tread**MOT #6** 2015-06-12 11:59**MOT test number** 308783965111**Result** ✓ Passed**Advice** Power steering fluid level low, but not below minimum (2.3.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #5

2015-06-12 11:59

MOT test number

917873265136

Result

✗ Failed

Pass with rectification Front registration plate deteriorated (6.3.1d)**Advice** Power steering fluid level low, but not below minimum (2.3.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #4

2014-06-16 15:29

MOT test number

425467064127

Result

✓ Passed

Notice Front number plate damaged**Notice** O/s/r light unit damaged

MOT #3

2014-06-16 11:35

MOT test number

246847964138

Result

✗ Failed

Fail Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Front number plate damaged**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** O/s/r light unit damaged



MOT #2	2013-06-17 09:16
MOT test number	275908763124
Result	✓ Passed

MOT #1	2012-05-31 08:45
MOT test number	639972452179
Result	✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
5 September 2023

✕
MOT

Expired:
13 September 2022

Tax status	Expired at 5 September
Days left	237 days too late
MOT expiry date	13 September 2022
Full MOT history	See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EK09ODG
Plate since	2019-03-29
Current registration	EK09ODG
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-06-17
Last registration	2021-09-09
Complete history	See info



Registration #1	2009-06-17	17 mi
Registration #2	2012-05-31	24.270 mi
Registration #3	2013-06-17	35.026 mi
Registration #4	2014-06-16	45.643 mi
Registration #5	2014-06-16	45.643 mi
Registration #6	2015-06-12	61.126 mi
Registration #7	2016-05-20	74.559 mi
Registration #8	2016-05-20	74.559 mi
Registration #9	2017-06-07	87.280 mi
Registration #10	2018-06-07	95.277 mi
Registration #11	2019-06-07	103.277 mi
Registration #12	2020-06-07	111.277 mi
Registration #13	2021-06-07	119.277 mi
Registration #14	2022-06-07	127.277 mi
Registration #15	2023-06-07	135.277 mi
Registration #16	2024-06-07	143.277 mi
Registration #17	2025-06-07	151.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2044 mm
Height	598 mm
Length	4278 mm
Kerb weight	1513 kg
Max. allowed weight	2240 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	9B12614