



report date: 2024-03-29

General information

Make	HONDA
Model	FR-V VTEC SPORT
Colour	Blue
Year of manufacture	-
Top speed	120 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	192 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-18
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history****MOT #19** 2022-07-02 08:01**MOT test number** 853241445194**Result** ✗ Failed

- Fail** Service brake lagging in operation (1.2.1 (d))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Rear Steering component mounting prescribed area is excessively corroded (2.1.2 (e) (i))
- Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))
- Fail** Offside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))
- Fail** Offside Rear Service brake excessively fluctuating (1.2.1 (e))
- Fail** Nearside Rear Steering component mounting prescribed area is excessively corroded (2.1.2 (e) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Front Exhaust has a major leak of exhaust gases cat corroded and has major leak (6.1.2 (a))
- Fail** Nearside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))

MOT #18 2021-07-20 14:42**MOT test number** 123069195640**Result** ✓ Passed**MOT #17** 2020-07-21 10:04**MOT test number** 490343588057**Result** ✓ Passed

**MOT #16** 2019-07-03 12:59**MOT test number** 968629729965**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Child Seat fitted not allowing full inspection of adult belt x3**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2018-07-11 07:50**MOT test number** 571016695415**Result** ✓ Passed**MOT #14** 2018-07-03 08:34**MOT test number** 709416634473**Result** ✗ Failed**Fail** Emissions not tested (8.2.1.2 (d))**Fail** Nearside Front Anti-roll bar linkage fractured drop link (5.3.3 (b) (ii))**Fail** Nearside Front Suspension arm pin or bush excessively worn front of (5.3.4 (a) (i))**Fail** Exhaust has a major leak of exhaust gases at front (6.1.2 (a))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front of (5.3.4 (a) (i))**MOT #13** 2017-07-24 12:47**MOT test number** 557967060887**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt 4

**MOT #12**

2017-07-20 08:49

MOT test number

594201905414

Result**✗ Failed****Advice** Child Seat fitted not allowing full inspection of adult belt 4**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 205/55/16 (4.1.D.1a)**Advice** Offside washer jet misses the windscreen**Fail** Nearside Rear Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #11**

2016-07-14 15:07

MOT test number

391136892754

Result**✓ Passed****Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #10**

2016-07-14 08:20

MOT test number

143125265975

Result**✗ Failed****Advice** Oil leak oil filter**Advice** Nearside Rear tyre worn on the outside**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front tyre worn on the outside**Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #9** 2015-07-13 11:38**MOT test number** 155194695180**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2014-07-25 12:30**MOT test number** 517166104256**Result** ✓ Passed**MOT #7** 2013-05-02 14:13**MOT test number** 918052823132**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #6** 2012-04-20 10:58**MOT test number** 168121612172**Result** ✓ Passed**MOT #5** 2012-04-19 16:07**MOT test number** 649350512177**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #4** 2011-05-18 12:30**MOT test number** 889628431126**Result** ✓ Passed



MOT #3	2011-05-18 10:46
MOT test number	289178031498
Result	✗ Failed
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Notice	Child seat fitted not allowing full inspection of adult belt

MOT #2	2010-05-27 12:43
MOT test number	570887240193
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt

MOT #1	2009-05-21 11:08
MOT test number	180921149106
Result	✓ Passed



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-03-24
Last registration	2022-07-02
Complete history	See info



Registration #1	2006-03-24	17 mi
Registration #2	2009-05-21	21.441 mi
Registration #3	2010-05-27	28.688 mi
Registration #4	2011-05-18	36.495 mi
Registration #5	2011-05-18	36.495 mi
Registration #6	2012-04-19	41.420 mi
Registration #7	2012-04-20	41.420 mi
Registration #8	2013-05-02	44.543 mi
Registration #9	2014-07-25	49.271 mi
Registration #10	2015-07-13	53.871 mi
Registration #11	2016-07-14	56.564 mi
Registration #12	2016-07-14	56.564 mi
Registration #13	2016-07-14	56.564 mi
Registration #14	2016-07-14	56.564 mi
Registration #15	2016-07-14	56.564 mi
Registration #16	2016-07-14	56.564 mi
Registration #17	2016-07-14	56.564 mi
Registration #18	2016-07-14	56.564 mi
Registration #19	2016-07-14	56.564 mi
Registration #20	2016-07-14	56.564 mi
Registration #21	2016-07-14	56.564 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2113 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1447 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Engine number	K20A92003809