





report date: 2024-03-29

General information

| Make | FORD |
|---------------------|-----------------------------|
| Model | RANGER REGULAR CAB 4X2 2.5D |
| Colour | Blue |
| Year of manufacture | - |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 77 BHP |
|-------------|---------------------|
| Max. torque | 168 Nm at 2.500 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |



CarCheck.co.uk page 1/10



MK04KPX report date: 2024-03-29

MOT history

| MOT #19 | 2020-10-29 11:43 |
|--|------------------|
| MOT test number | 891461212745 |
| Result | ✓ Passed |
| Next expiry date | 2021-10-28 |
| Advice Underside of vehicle has surface corrossion | |

| MOT #18 | 2019-10-10 12:29 |
|--|------------------|
| MOT test number | 811154632003 |
| Result | ✓ Passed |
| | |
| MOT #17 | 2018-10-01 13:44 |
| MOT test number | 648098398036 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| Advice | Offside Rear Leaf spring has slight wear in an anchor pin and/or bush (5.3.4 (a) (i)) |
|--------|--|
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Rear Leaf spring has slight wear in an anchor pin and/or bush (5.3.4 (a) (i)) |
| | |

| MOT #16 | 2017-09-18 10:14 |
|---|------------------|
| MOT test number | 510877504720 |
| Result | ✓ Passed |
| Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |

CarCheck.co.uk page 2/10



report date: 2024-03-29

MOT test number

Sesult

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Stop lamp not working (1.2.1b)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #14 2016-09-12 10:39

MOT test number 475521413428

Result ✓ Passed

MOT #13 2015-09-08 12:16

MOT test number 931562613411

Result ✓ Passed

MOT #12 2014-09-15 11:25

MOT test number 205538354276

Result \(\sqrt{Passed} \)

Advice Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #11 2013-04-09 14:01

MOT test number 568219793077

CarCheck.co.uk page 3/10



report date: 2024-03-29

 MOT #10
 2013-04-09 14:01

 MOT test number
 318769593016

 Result
 X Failed

Pass with rectification

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification

Nearside Front Windscreen wiper does not clear the windscreen effectively

(8.2.2)

MOT #9

MOT test number

579360412162

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Fail Nearside front brake binding (3.7.B.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Brakes imbalanced across an axle (3.7.B.5b)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #7
 2011-03-10 14:09

 MOT test number
 287439761096

 Result
 ✓ Passed

 MOT #6
 2010-03-08 14:01

 MOT test number
 762047160087

 Result
 ✓ Passed

CarCheck.co.uk page 4/10



report date: 2024-03-29

MOT #5 2009-03-11 15:12

MOT test number 383280979009

Result
✓ Passed

MOT #4 2009-03-10 17:16

MOT test number 881339469005

Result X Failed

Fail Offside Rear fog lamp not working (1.3.2b)

MOT #3 2008-03-11 16:55

MOT test number 532831478012

Result ✓ Passed

MOT #2 2007-03-09 16:06

MOT test number 884168867008

Result
✓ Passed

MOT #1 2007-03-07 12:18

MOT test number 141476567089

Result X Failed

Fail Offside Front Mechanical brake component has restricted free movement (3.5.1k)

Fail Brakes imbalanced across an axle (3.7.B.5b)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Centre Exhaust system not adequately supported (7.1.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front brake disc excessively scored (3.5.1h)

CarCheck.co.uk page 5/10



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-29

Owner history

| For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report | |
|--|-------------|
| | |
| | |
| | |
| *************************************** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | , |
| Current registration | NK SIN |
| Plate since | |
| Current registration | OK SIN |
| Plate since | |
| | More info > |

CarCheck.co.uk page 7/10



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 19 |
| First mileage registration | 2004-03-01 |
| Last registration | 2020-10-29 |
| Complete history | See info |



| Registration #1 | 2004-03-01 | 11 mi |
|------------------|------------|-----------|
| Registration #2 | 2007-03-07 | 45.383 mi |
| Registration #3 | 2007-03-09 | 45.383 mi |
| Registration #4 | 2008-03-11 | 55.859 mi |
| Registration #5 | 2009-03-10 | 59.131 mi |
| Registration #6 | 2009-03-11 | 59.131 mi |
| Registration #7 | 2010-03-08 | 61.968 mi |
| Registration #8 | 2011-03-10 | 63.405 mi |
| Registration #9 | 2012-04-16 | 64.711 mi |
| Registration #10 | 2012-04-19 | 64.711 mi |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 91.777 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 11.777 es |
| Registration #18 | | 0.77 44 |
| Registration #19 | | |

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-29

Car features

| 50225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Dimensions & weight

| Width | 1695 mm |
|-------------|---------|
| Height | 1615 mm |
| Length | 4998 mm |
| Kerb weight | 1490 kg |

Additional information

| Fuel tank capacity | 70 |
|--------------------|--------------------|
| Fuel delivery | Indirect Injection |
| Number of doors | 2 |
| Engine number | 433508 |

CarCheck.co.uk page 10/10