



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA DESIRE 16V PICASSO E4
Colour	Black
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-30
Pictures	6
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #22	2023-05-02 16:24
MOT test number	659990169525
Result	✓ Passed
Next expiry date	2024-05-05
Advice	Nearside Front Play in steering rack inner joint(s)

MOT #21	2023-05-02 11:45
MOT test number	855650285149
Result	✗ Failed
Advice	Nearside Front Play in steering rack inner joint(s)
Fail	Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Could not assess front pads due to wheel trims
Fail	Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MOT #20	2022-04-27 13:52
MOT test number	468351997167
Result	✓ Passed
Advice	Rear Exhaust mounting defective (6.1.2 (a))

**MOT #19**

2022-04-27 11:18

MOT test number

477694209255

Result

✗ Failed

- Fail** Offside Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Headlamp aim too low (4.1.2 (a))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #18

2021-05-06 11:40

MOT test number

269633150551

Result

✓ Passed

MOT #17

2020-08-12 08:37

MOT test number

579654763288

Result

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Cracking in tread (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases Front to center joint (6.1.2 (a))

**MOT #16**

2020-08-07 10:47

MOT test number

809187582846

Result**✗ Failed**

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Cracking in tread (5.2.3 (d) (ii))

Advice Power steering pipe/hose has slight seepage (2.1.5 (a))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Cracked to cords (5.2.3 (d) (i))

Fail Offside Seat belt anchorage prescribed area strength or continuity significantly reduced Sill (7.1.1 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))

Advice Exhaust has a minor leak of exhaust gases Front to center joint (6.1.2 (a))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced Sill (7.1.1 (a) (i))

Fail Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #15

2019-08-07 10:50

MOT test number

953400538649

Result**✓ Passed**

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner sidewall cracking (5.2.3 (e))

MOT #14

2019-08-07 10:50

MOT test number

588781531152

Result**✗ Failed**

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner sidewall cracking (5.2.3 (e))

Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #13** 2018-08-06 15:27**MOT test number** 702111636537**Result** ✓ Passed**MOT #12** 2018-08-06 15:27**MOT test number** 153390149186**Result** ✗ Failed

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #11 2017-08-02 15:04**MOT test number** 945636017027**Result** ✓ Passed

Advice Offside Front tyre worn on edge

MOT #10 2017-08-02 12:06**MOT test number** 455705691093**Result** ✗ Failed

Advice Offside Front tyre worn on edge

Fail Offside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #9 2016-08-01 14:09**MOT test number** 255548406418**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2016-08-01 11:33**MOT test number** 774939880355**Result** ✗ Failed**Fail** Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. 185/65/15 (4.1.A.1a)**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #7** 2015-08-07 08:56**MOT test number** 966059915222**Result** ✓ Passed**Notice** Nearside front tyre sidewall starting to crack**Notice** Rear exhaust mount strap broken but exhaust is supported ok.**MOT #6** 2014-08-04 12:16**MOT test number** 648596014285**Result** ✓ Passed**Notice** Nearside front tyre low on outer edge**MOT #5** 2014-08-04 12:16**MOT test number** 245726714299**Result** ✗ Failed**Notice** Nearside front tyre low on outer edge**Pass with rectification** Offside Stop lamp not working (1.2.1b)

**MOT #4** 2013-08-08 15:16**MOT test number** 257050223237**Result** ✓ Passed**MOT #3** 2012-07-16 14:24**MOT test number** 445838392176**Result** ✓ Passed**Notice** Both rear tyres are perishing**MOT #2** 2012-07-16 10:33**MOT test number** 669198692154**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** N/s/f and o/s/f tyres perishing**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #1** 2011-07-01 12:16**MOT test number** 829562081166**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-07-31
Last registration	2023-05-02
Complete history	See info



Registration #1	2008-07-31	27 mi
Registration #2	2011-07-01	40.012 mi
Registration #3	2012-07-16	49.174 mi
Registration #4	2012-07-16	49.174 mi
Registration #5	2013-08-08	58.848 mi
Registration #6	2014-08-04	65.107 mi
Registration #7	2015-08-07	71.007 mi
Registration #8	2016-08-01	76.633 mi
Registration #9	2016-08-01	76.633 mi
Registration #10	2017-08-02	80.854 mi
Registration #11	2017-08-02	80.854 mi
Registration #12	2018-08-06	83.648 mi
Registration #13	2019-05-20	85.277 mi
Registration #14	2019-05-20	85.277 mi
Registration #15	2019-05-20	85.277 mi
Registration #16	2019-05-20	85.277 mi
Registration #17	2019-05-20	85.277 mi
Registration #18	2019-05-20	85.277 mi
Registration #19	2019-05-20	85.277 mi
Registration #20	2019-05-20	85.277 mi
Registration #21	2019-05-20	85.277 mi
Registration #22	2019-05-20	85.277 mi
Registration #23	2019-05-20	85.277 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX7U3348217