





report date: 2024-03-28

General information

| Make | BMW |
|---------------------|-----------------------------|
| Model | 435 435I M SPORT GRAN COUPE |
| Colour | White |
| Year of manufacture | 2014 |
| Top speed | 155 mph |
| 0 - 60 mph | 5.2 seconds |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| Power | 302 BHP |
|-------------------------|---------------------|
| Max. torque | 400 Nm at 1.200 rpm |
| Engine capacity | 2.979 сс |
| Cylinders | 6 |
| Fuel type | Petrol |
| Consumption city | 25.7 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 37.2 mpg |
| CO2 emission | 178 g/km |
| CO2 label | 1 |



CarCheck.co.uk page 1/12



Internet history

Entry 3

Date 2024-01-16


Pictures 34

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date 2022-12-14

Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-06-29

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2025-01-31 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 8 |
| Failed MOT tests | 2 |
| Total advice items | 9 |
| Total items failed | 5 |

| MOT #10 | 2024-02-01 14:22 |
|------------------|------------------|
| MOT test number | 281162336404 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-31 |

| MOT #9 | 2023-07-31 12:53 |
|-----------------|--|
| MOT test | number 437576823937 |
| Result | ✓ Passed |
| Advice (a) (i)) | Nearside Front Lower Suspension arm ball joint has slight play rear arm, becoming excessive (5.3.4 |
| Advice | Engine cover and undertrays fitted obscuring view of testable items |

| MOT #8 | 2022-07-29 13:26 |
|-----------------|------------------|
| MOT test number | 850077977981 |
| Result | ✓ Passed |
| | |

| MOT #7 | 2021-07-15 07:57 |
|-----------------|------------------|
| MOT test number | 448570365264 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/12



Result

YE64FLG report date: 2024-03-28

× Failed

MOT #6 2020-09-26 15:22

MOT test number 736709211648

Result \(\sqrt{Passed} \)

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #5 2020-09-26 09:20

MOT test number 422101997270

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Brake fluid warning lamp illuminated (1.1.10 (f))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2019-10-25 15:52

MOT test number 728820548554

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3 2019-10-25 13:24

MOT test number 433731419443

Result × Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 4/12



| MOT #2 | 2018-10-23 14:20 |
|-----------------|------------------|
| MOT test number | 445722913665 |

MOT #1 2017-10-02 08:33
MOT test number 995750855711

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 August |
|------------------|----------------------|
| Days left | 93 |
| MOT expiry date | 31 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | T |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| , | | |
|--|-----------|-----|
| For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report I | | ve? |
| | | |
| | | |
| | | |
| | | |
| ******* | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes See in this check if this BMW had different number plates. | | |
| Number of plates | | , |
| Current registration | NK SIES | |
| Plate since | | |
| Current registration | NK Nie | |
| Plate since | | |
| | More info | > |
| | | |

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2014-11-10 |
| Last registration | 2024-02-01 |
| Complete history | See info |



| Registration #1 | 2014-11-10 | 23 mi |
|-----------------------------------|------------|--|
| Registration #2 | 2017-10-02 | 25.263 mi |
| Registration #3 | 2018-10-23 | 35.267 mi |
| Registration #4 | 2019-10-25 | 40.297 mi |
| Registration #5 | 2019-10-25 | 40.297 mi |
| Registration #6 | 2020-09-26 | 45.494 mi |
| Registration #7 | 2020-09-26 | 45.494 mi |
| Registration #8 | | 77,777 44 |
| | | |
| Registration #9 | | 11.777 es |
| Registration #9 Registration #10 | | 11.777 es |
| | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #10 Registration #11 | | 77,777-66 77,777-66 77,777-66 77,777-66 |

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| 50501 | |
| S0566 | |
| S0567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 95% |
| Children | 84% |
| Pedestrian | 78% |
| Safety systems | 86% |
| Overall rating | 89% |
| Video | see crash video |



Dimensions & weight

| Width | 1825 mm |
|---------------------|---------|
| Height | 1397 mm |
| Length | 4638 mm |
| Wheel base | 2810 mm |
| Kerb weight | 1585 kg |
| Max. allowed weight | 2145 kg |

Additional information

| Fuel tank capacity | 60 I | |
|-----------------------------------|------------------|-------|
| Fuel delivery | Direct Injection | |
| Number of doors | 4 | |
| Number of seats CarCheck.co.uk | 5 page | 12/12 |

Number of axles 2

Engine number 06948900