



RV63HNNH

report date: 2024-03-28

General information

Make	FORD
Model	B-MAX TITANIUM
Colour	Silver
Year of manufacture	2013
Top speed	117 mph
0 - 100 km/h	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 kW / 101 HP / 118 BHP
Max. torque	170 Nm at 1.400 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.7 mpg
CO2 emission	114 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-07-16
Pictures	31
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-04
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	27
Total items failed	2

MOT #12	2023-07-03 15:31
MOT test number	410581888922
Result	✓ Passed
Next expiry date	2024-07-04
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11	2023-07-03 14:34
MOT test number	520056507642
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2022-07-04 16:50
MOT test number	870816496609
Result	✓ Passed
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))



MOT #9	2022-07-02 11:24
MOT test number	180735527365
Result	✗ Failed
MAJOR	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

MOT #8	2021-07-05 15:54
MOT test number	153004962860
Result	✓ Passed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge compound showing (5.2.3 (e))
Minor	Offside Rear Lower Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge compound showing (5.2.3 (e))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))

**MOT #7**

2021-07-01 09:53

MOT test number

294758056947

Result**✗ Failed****MAJOR** Nearside Front Headlamp insecure (4.1.1 (c))**Minor** Offside Rear Lower Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**MAJOR** Front Exhaust has a major leak of exhaust gases flexi joint (6.1.2 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge compound showing (5.2.3 (e))**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge compound showing (5.2.3 (e))**MOT #6**

2020-06-10 15:42

MOT test number

171579217361

Result**✓ Passed****Advice** Exhaust flexi coupling deteriorated.**MOT #5**

2019-04-29 10:20

MOT test number

146707121054

Result**✓ Passed****MOT #4**

2018-04-16 14:51

MOT test number

182325596117

Result**✓ Passed**



MOT #3	2018-04-16 14:51
MOT test number	177283214687
Result	✗ Failed
Pass with rectification	Offside Stop lamp not working (1.2.1b)
Pass with rectification	Nearside Stop lamp not working (1.2.1b)

MOT #2	2017-04-25 10:12
MOT test number	916499011538
Result	✓ Passed

MOT #1	2016-05-04 15:18
MOT test number	190525001144
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
4 July 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	4 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	RV63HNNH
Plate since	2019-03-28
Current registration	RV63HNNH
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-10-31
Last registration	2023-07-03
Complete history	See info



Registration #1	2013-10-31	29 mi
Registration #2	2016-05-04	7.812 mi
Registration #3	2017-04-25	21.086 mi
Registration #4	2018-04-16	39.316 mi
Registration #5	2018-04-16	39.316 mi
Registration #6	2019-04-29	56.466 mi
Registration #7	2020-06-10	73.535 mi
Registration #8	2021-06-29	91.577 mi
Registration #9	2022-06-29	109.619 mi
Registration #10	2023-06-29	127.661 mi
Registration #11	2023-06-29	127.661 mi
Registration #12	2023-06-29	127.661 mi
Registration #13	2023-06-29	127.661 mi
Registration #14	2023-06-29	127.661 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1760 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	DK03316