



report date: 2024-03-29

General information

Make	NISSAN
Model	NOTE DCI TEKNA
Colour	Black
Year of manufacture	2015
Top speed	111 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	88.3 mpg
Consumption combined	78.5 mpg
CO2 emission	90 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-02-03
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-01-09
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	32
Total items failed	7

MOT #7	2024-01-10 10:19
MOT test number	214171265784
Result	✓ Passed
Next expiry date	2025-01-09
Advice	Rear Tyre worn close to legal limit/worn on edge both nearside and offside (5.2.3 (e))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #6	2024-01-10 10:19
MOT test number	361334514000
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Rear Tyre worn close to legal limit/worn on edge both nearside and offside (5.2.3 (e))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #5**

2023-02-03 12:45

MOT test number

490716152946

Result

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside day time running light not working
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4

2022-02-04 15:09

MOT test number

369701869173

Result

✓ Passed

- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Offside daytime lamp not working
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Items removed from driver's view prior to test
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #3**

2022-02-04 15:09

MOT test number

260023901067

Result**✗ Failed**

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Pass with rectification** Windscreen washer not working both (3.5 (a))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside daytime lamp not working
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Items removed from driver's view prior to test
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #2

2021-02-11 17:41

MOT test number

329180884296

Result**✓ Passed**



MOT #1	2021-02-09 15:30
MOT test number	333966565617
Result	✗ Failed
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
9 January 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	9 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-01-01
Last registration	2024-01-10
Complete history	See info



Registration #1	2015-01-01	20 mi
Registration #2	2015-05-01	25,000 mi
Registration #3	2021-02-09	65.771 mi
Registration #4	2021-02-11	65.774 mi
Registration #5	2022-02-04	75.372 mi
Registration #6	2022-05-01	75,000 mi
Registration #7	2022-08-01	75,000 mi
Registration #8	2023-05-01	75,000 mi
Registration #9	2024-01-10	75,000 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	82%
Pedestrian	58%
Safety systems	70%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1530 mm
Length	4100 mm
Wheel base	2600 mm
Kerb weight	1129 kg
Max. allowed weight	1615 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D421005