



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	308 S/S ALLURE
Colour	Grey
Year of manufacture	2017
Top speed	125 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	48.7 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	107 g/km
CO2 label	B





Internet history

Entry 2


Date	2021-06-27
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-06-25
Pictures	32
Listing price	View report



source: [heycar.co.uk](#)

**MOT history**

MOT expiry date	2024-06-04
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	28
Total items failed	1

MOT #6	2023-06-01 08:38
---------------	------------------

MOT test number	103658283848
------------------------	--------------

Result	✓ Passed
---------------	----------

Next expiry date	2024-06-04
-------------------------	------------

Advice Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm of tread (1.6mm is the minimum legal requirement) bald on both edges of the tread area, deep cut in tread also and damaged on outer sidewall, poor condition i would recommend replacement! (5.2.3 (e))

Advice Inner Road wheel slightly distorted all 4 wheels (5.2.2 (c) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2mm of tread (1.6mm is the minimum legal requirement) bald on both edges of the tread area, deep cut in tread also and damaged on outer sidewall, poor condition i would recommend replacement! (5.2.3 (e))

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Wishbone rear bushes both sides of the vehicle are splitting from the bush housings and are also perished and cracked (5.3.4 (a) (i))

Advice Nearside Rear Outer Tyre slightly damaged sidewall (5.2.3 (d) (ii))

Advice Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))

**MOT #5**

2023-06-01 08:08

MOT test number

804139606308

Result

✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2mm of tread (1.6mm is the minimum legal requirement) bald on both edges of the tread area, deep cut in tread also and damaged on outer sidewall, poor condition i would recommend replacement! (5.2.3 (e))

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Wishbone rear bushes both sides of the vehicle are splitting from the bush housings and are also perished and cracked (5.3.4 (a) (i))

Advice Nearside Rear Outer Tyre slightly damaged sidewall (5.2.3 (d) (ii))

Advice Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))

Fail Central Rear Seat belt likely to become detached in the event of a collision lower seat belt bolt missing so belt is not bolted to the floor (seat belt un-usable). (7.1.1 (a) (ii))

Advice Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge 2mm of tread (1.6mm is the minimum legal requirement) bald on both edges of the tread area, deep cut in tread also and damaged on outer sidewall, poor condition i would recommend replacement! (5.2.3 (e))

Advice Inner Road wheel slightly distorted all 4 wheels (5.2.2 (c) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

MOT #4

2022-06-01 08:06

MOT test number

624281739662

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Items removed from driver's view prior to test Phone holder

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Nail in tyre Nail/pin or similar

MOT #3

2021-05-24 08:34

MOT test number

188640861659

Result

✓ Passed

Advice Items removed from driver's view prior to test

**MOT #2** 2020-06-05 11:48**MOT test number** 656963162587**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Nail in tyre 2 nails
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Small stone chips to windscreen
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2020-05-22 06:16**MOT test number** 691237419606**Result** ✓ Passed

- Advice** COVID-19 6 MONTH EXTENSION



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
4 June 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	4 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	EK17RZB
Plate since	2019-03-28
Current registration	EK17RZB
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-05-30
Last registration	2023-06-01
Complete history	See info



Registration #1	2017-05-30	26 mi
Registration #2	2020-06-05	31.505 mi
Registration #3	2021-05-24	41.241 mi
Registration #4	2022-05-29	51.277 mi
Registration #5	2023-05-29	61.277 mi
Registration #6	2023-05-29	71.277 mi
Registration #7	2023-05-29	81.277 mi
Registration #8	2023-05-29	91.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	79%
Pedestrian	64%
Safety systems	81%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1804 mm
Height	1457 mm
Length	4253 mm
Wheel base	2620 mm
Kerb weight	1150 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	XTA10515224