



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 SPORT HDI
Colour	Blue
Year of manufacture	-
Top speed	129 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN

**MOT history****MOT #16**

2023-11-29 12:16

MOT test number

362141593961

Result**✗ Failed**

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- MAJOR** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced floor to sill (7.1.1 (a) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Inner Steering linkage ball joint has excessive play drum stick (2.1.3 (b) (i))
- MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Nearside Front Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced floor (7.1.1 (a) (i))

MOT #15

2022-11-18 10:35

MOT test number

727372995160

Result**✓ Passed**

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Inner Track rod end ball joint has slight play drum stick (2.1.3 (b) (i))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #14**

2022-11-18 10:08

MOT test number

417500312074

Result**✗ Failed****MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Inner Track rod end ball joint has slight play drum stick (2.1.3 (b) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #13**

2021-06-04 15:03

MOT test number

858780968432

Result**✓ Passed****Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Play in steering rack inner joint(s)**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #12**

2021-05-15 08:48

MOT test number

747676193150

Result**✗ Failed**

Advice Nearside Play in steering rack inner joint(s)

MAJOR Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Front Bush (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Front Bush (5.3.4 (a) (i))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #11** 2020-05-14 11:07**MOT test number** 916594814322**Result** ✓ Passed**Advice** Nearside Rear Brake hose has slight corrosion to ferrule from body (1.1.12 (f) (i))**Advice** Nearside Play in steering rack inner joint(s)**Advice** Offside Rear Brake hose has slight corrosion to ferrule from body (1.1.12 (f) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 205/50W17 (5.2.3 (e))**MOT #10** 2019-04-29 09:52**MOT test number** 592436553622**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 205/50ZR17 (5.2.3 (e))**MOT #9** 2018-05-09 07:44**MOT test number** 579760867890**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #8** 2018-05-04 12:17**MOT test number** 888712027533**Result** ✗ Failed**Fail** Rear brake binding both (3.7.B.1)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)

**MOT #7** 2018-03-17 12:02**MOT test number** 349177107047**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Play in steering rack inner joint(s)

MOT #6 2017-03-28 17:40**MOT test number** 774980944619**Result** ✓ Passed

- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)
- Advice** Rear discs slightly corroded
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #5 2016-03-15 14:26**MOT test number** 504144581734**Result** ✓ Passed

- Advice** All four brake discs slightly corroded

MOT #4 2015-04-22 11:21**MOT test number** 947932415125**Result** ✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)



MOT #3	2014-05-02 14:53
MOT test number	398332824156
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2013-03-20 08:52
MOT test number	116669173080
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Both rear tyres scrubbed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Nail in offside rear tyre
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2012-03-31 11:42
MOT test number	629181092079
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-03-31
Last registration	2023-11-29
Complete history	See info



Registration #1	2009-03-31	15 mi
Registration #2	2012-03-31	26.146 mi
Registration #3	2013-03-20	39.113 mi
Registration #4	2014-05-02	50.596 mi
Registration #5	2015-04-22	62.989 mi
Registration #6	2016-03-15	68.378 mi
Registration #7	2017-03-28	73.129 mi
Registration #8	2018-03-17	76.355 mi
Registration #9	2018-05-04	76.757 mi
Registration #10	2019-05-29	76.757 mi
Registration #11	2019-05-29	76.757 mi
Registration #12	2019-05-29	76.757 mi
Registration #13	2019-05-29	76.757 mi
Registration #14	2019-05-29	76.757 mi
Registration #15	2019-05-29	76.757 mi
Registration #16	2019-05-29	76.757 mi
Registration #17	2019-05-29	76.757 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Kerb weight	1653 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	DYUK4107676