



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 SE LUX
Colour	Silver
Year of manufacture	2009
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I






Internet history

Entry 2

Date	2021-08-10
Pictures	18
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-07-31
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-14
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	19
Total items failed	20

MOT #18	2024-01-18 17:06
MOT test number	157141010857
Result	✓ Passed
Next expiry date	2025-02-14
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Service brake binding but not excessively (Pads Low) (1.2.1 (f))

**MOT #17**

2024-01-17 11:55

MOT test number

138430772159

Result**✗ Failed**

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps Both sides inoperative . (4.7.1 (b) (ii))

Fail Central Front Exhaust silencer likely to become detached (8.1.1 (b) (ii))

Fail Offside Front Headlamp levelling device inoperative Detached from its mounting (4.1.5 (a))

Advice Nearside Rear Service brake binding but not excessively (Pads Low) (1.2.1 (f))

Fail Central Front Exhaust has a major leak of exhaust gases (6.1.2 (a))

Fail Rear Brake hose ferrule excessively corroded Both sides. (1.1.12 (f) (i))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Emissions unable to be completed Exhaust system detached. (8.2.1.2 (d))

Fail Central Exhaust system insecure (6.1.2 (a))

MOT #16

2023-02-15 17:27

MOT test number

724399967532

Result**✓ Passed**

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #15**

2023-01-13 18:09

MOT test number

566818351159

Result

✗ Failed

Fail Offside Front Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction Carrier fitted on windscreen (3.1 (a) (ii))

Fail Offside Front Power steering pipe/hose excessively corroded Steering rack fixing (2.1.5 (g) (i))

Fail Emissions not tested Could not complete due to excessive escape of exhaust gases effecting the Lambda reading see emissions sheet (8.2.1.2 (d))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Front Headlamp aim too low Both sides. (4.1.2 (a))

Fail Front Sub-frame corroded and seriously weakened Steering rack mounting, (5.3.3 (b) (i))

Fail Rear Exhaust has a major leak of exhaust gases Exhaust box and Front Flex joint. (6.1.2 (a))

Advice Coolant radiator carrier rotted away,

MOT #14

2021-07-28 11:22

MOT test number

467329584077

Result

✓ Passed

MOT #13

2020-10-08 13:57

MOT test number

646110381178

Result

✓ Passed

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #12

2019-10-08 08:03

MOT test number

576414947621

Result

✓ Passed

MOT #11

2018-10-04 09:47

MOT test number

686639382168

Result

✓ Passed

**MOT #10** 2018-10-02 08:11**MOT test number** 185088356114**Result** ✗ Failed**Fail** Nearside Front Outer Position lamp not working (4.2.1 (a))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2017-10-11 14:33**MOT test number** 164723194232**Result** ✓ Passed**MOT #8** 2017-10-06 08:35**MOT test number** 698181833742**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Central Front Exhaust system not adequately supported (7.1.1)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #7** 2016-10-06 15:24**MOT test number** 759830008000**Result** ✓ Passed**MOT #6** 2016-04-21 13:23**MOT test number** 334326524585**Result** ✓ Passed

**MOT #5** 2015-04-15 14:50**MOT test number** 765115305113**Result** ✓ Passed

- Notice** Offside front tyre bald on inner edge
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nearside rear tyre cracked / perished
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Nearside front tyre cracked / perished
- Notice** Nearside front tyre bald on inner edge
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Offside rear tyre cracked / perished
- Notice** Offside front tyre cracked / perished

MOT #4 2014-04-18 10:42**MOT test number** 368238204129**Result** ✓ Passed**MOT #3** 2014-04-17 14:29**MOT test number** 188287104199**Result** ✗ Failed

- Fail** Parking brake lever has no reserve travel (3.1.6b)

MOT #2 2013-04-17 11:42**MOT test number** 566907603172**Result** ✓ Passed



MOT #1	2012-04-10 11:52
MOT test number	228581602468
Result	✓ Passed
<div><div>Advice</div>Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)</div>	



Tax & MOT check

X

Untaxed

Tax expired:
20 February 2024

✓

MOT

Expires:
14 February 2025

Tax status	Expired at 20 February 2024
Days left	68 days too late
MOT expiry date	14 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	SL09UKP
Plate since	2024-03-28
Current registration	SL09UKP
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-04-30
Last registration	2024-01-18
Complete history	See info



Registration #1	2009-04-30	25 mi
Registration #2	2012-04-10	16.744 mi
Registration #3	2013-04-17	22.538 mi
Registration #4	2014-04-17	28.993 mi
Registration #5	2014-04-18	28.993 mi
Registration #6	2015-04-15	38.678 mi
Registration #7	2016-04-21	49.755 mi
Registration #8	2016-10-06	55.459 mi
Registration #9	2017-10-06	60.664 mi
Registration #10	2017-10-11	60.667 mi
Registration #11	2018-10-02	63.876 mi
Registration #12	2019-05-20	65.277 mi
Registration #13	2019-05-20	65.277 mi
Registration #14	2019-05-20	65.277 mi
Registration #15	2019-05-20	65.277 mi
Registration #16	2019-05-20	65.277 mi
Registration #17	2019-05-20	65.277 mi
Registration #18	2019-05-20	65.277 mi
Registration #19	2019-05-20	65.277 mi
Registration #20	2019-05-20	65.277 mi
Registration #21	2019-05-20	65.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1344 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	175195