



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Silver
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	H







Internet history

Entry 1

Date	2021-08-10
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-16
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	40
Total items failed	22

MOT #20	2023-08-17 09:40
MOT test number	680943941062
Result	✓ Passed
Next expiry date	2024-08-16
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall (5.2.3 (d) (i))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall (5.2.3 (d) (i))

**MOT #19**

2023-08-08 11:00

MOT test number

460968611199

Result

✗ Failed

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall (5.2.3 (d) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Emissions unable to be completed Large exhaust leak. not enough gasses from exhaust to allow probe pickup. (8.2.1.2 (d))**Fail** Exhaust noise is clearly in excess of that emitted by a similar vehicle fitted with a standard silencer in average condition Caused by exhaust leak (8.1.1 (a))**Fail** Fuel cap/sealing device ineffective Broken (6.1.3 (b) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords Outer sidewall (5.2.3 (d) (i))**Fail** Exhaust emissions likely to be affected by an exhaust leak From front flexi (8.2.1.1 (b))**MOT #18**

2022-08-08 10:29

MOT test number

244924563184

Result

✓ Passed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Central rear seatbelt jamming occasionally but still functioning as intended**MOT #17**

2021-08-09 12:26

MOT test number

977141576926

Result

✓ Passed

**MOT #16** 2020-10-26 14:31**MOT test number** 627843553197**Result** ✓ Passed**Advice** Judder recorded from the O/S/F brake. Brake is binding.**Advice** Exhaust is vibrating on the floorpan.**MOT #15** 2020-10-24 10:02**MOT test number** 498104088194**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed Cut in the tread (5.2.3 (d) (ii))**Advice** Exhaust is vibrating on the floorpan.**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Judder recorded from the O/S/F brake. Brake is binding.**MOT #14** 2019-10-19 15:19**MOT test number** 488931422207**Result** ✓ Passed**Advice** Offside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Exhaust is touching the floor

**MOT #13**

2019-10-19 14:24

MOT test number

577717462965

Result**✗ Failed****Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Exhaust is touching the floor**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #12**

2018-10-20 15:23

MOT test number

395328428758

Result**✓ Passed****Minor** Offside Front Windscreen wiper blade defective starting to smear (3.4 (b) (i))**Advice** Nearside Front tyre wearing on inner edge**Advice** Offside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Minor** Nearside Front Windscreen wiper blade defective spoiler hitting windscreen and starting to smear (3.4 (b) (i))**Advice** New exhaust fitted hitting floor**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #11**

2017-10-21 14:03

MOT test number

908501900509

Result**✓ Passed****Advice** N/S/F outer brake pad is worn extremely low.**Advice** Rear tyres are wearing low on the inner edges.

**MOT #10**

2017-10-20 15:56

MOT test number

917450608754

Result**✗ Failed****Advice** N/S/F outer brake pad is worn extremely low.**Fail** Front Exhaust has a major leak of exhaust gases Flexi (7.1.2)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Rear tyres are wearing low on the inner edges.**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #9**

2016-10-05 15:59

MOT test number

776854415988

Result**✓ Passed****Advice** Slight leak from front exhaust**MOT #8**

2016-10-05 08:44

MOT test number

215973000553

Result**✗ Failed****Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Slight leak from front exhaust**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear brake discs worn

**MOT #7** 2015-10-14 07:43**MOT test number** 255261160116**Result** ✓ Passed**MOT #6** 2014-10-14 11:36**MOT test number** 885247384227**Result** ✓ Passed**Notice** Rear tyres worn on inner edges & side walls perishing.**MOT #5** 2014-10-14 11:36**MOT test number** 699017084284**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Notice** Rear tyres worn on inner edges & side walls perishing.**MOT #4** 2013-10-15 08:48**MOT test number** 236698683254**Result** ✓ Passed**Notice** Rear tyres wearing on edges**Notice** Front tyres getting low on tread**MOT #3** 2012-10-23 17:14**MOT test number** 977157592208**Result** ✓ Passed**Notice** Chips in windsreen,nearside rear tyre wearing on edges**Notice** Exhaust bracket broken,still secure



MOT #2	2012-10-19 09:30
MOT test number	377553092292
Result	✗ Failed
Notice	Exhaust bracket broken,still secure
Notice	Chips in windsreen,nearside rear tyre wearing on edges
Fail	Offside Rear coil spring cracked (2.4.C.1a)

MOT #1	2011-02-24 14:57
MOT test number	556965951043
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
16 August 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	16 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 SH08CNK
Plate since	2024-03-28
Current registration	 SH08CNK
Plate since	2024-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-04-04
Last registration	2023-08-17
Complete history	See info



Registration #1	2008-04-04	27 mi
Registration #2	2011-02-24	16.778 mi
Registration #3	2012-10-19	34.435 mi
Registration #4	2012-10-23	34.438 mi
Registration #5	2013-10-15	44.494 mi
Registration #6	2014-10-14	52.152 mi
Registration #7	2015-10-14	59.237 mi
Registration #8	2016-10-05	66.112 mi
Registration #9	2016-10-05	66.112 mi
Registration #10	2017-10-20	84.844 mi
Registration #11	2017-10-21	84.844 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2019-05-20	95.277 mi
Registration #16	2019-05-20	95.277 mi
Registration #17	2019-05-20	95.277 mi
Registration #18	2019-05-20	95.277 mi
Registration #19	2019-05-20	95.277 mi
Registration #20	2019-05-20	95.277 mi
Registration #21	2019-05-20	95.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564