



DU63JYW

report date: 2024-03-28

General information

Make	FORD
Model	FOCUS
Colour	White
Year of manufacture	2013
Gearbox	-

Engine & fuel consumption

Engine capacity	1.560 cc
Fuel type	Diesel
CO2 emission	109 g/km
CO2 label	B






Internet history

Entry 2


Date	2022-05-06
Pictures	29
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-05-28
Pictures	28
Listing price	View report



source: theaa.com



MOT history

MOT expiry date	2025-04-26
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	32
Total items failed	4

MOT #12	2024-04-15 11:21
MOT test number	216751616757
Result	✓ Passed
Next expiry date	2025-04-26
Advice	Offside Front Play in steering rack inner joint(s) Steering rack end

MOT #11	2024-04-15 08:31
MOT test number	638658783088
Result	✗ Failed
Fail	Offside Rear Suspension arm pin or bush excessively worn Trailing arm bush (5.3.4 (a) (i))
Advice	Offside Front Play in steering rack inner joint(s) Steering rack end
Fail	Nearside Rear Suspension arm pin or bush excessively worn Trailing arm bush (5.3.4 (a) (i))

MOT #10	2023-04-03 09:15
MOT test number	518581454311
Result	✓ Passed
Advice	Suspension arm pin or bush worn but not resulting in excessive movement offside and nearside trailing arm bushes (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
Advice	Offside Front Steering linkage ball joint has slight play inner rack end (2.1.3 (b) (i))

**MOT #9** 2022-04-27 16:55**MOT test number** 879296355943**Result** ✓ Passed**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Offside Play in steering rack inner joint(s)**MOT #8** 2021-05-29 10:45**MOT test number** 830310703403**Result** ✓ Passed**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7** 2021-05-28 11:50**MOT test number** 657678556393**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Horn not working (7.7 (a) (ii))**MOT #6** 2020-09-21 11:45**MOT test number** 979451055441**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5**

2019-10-14 08:28

MOT test number

694702208084

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both Sides (1.1.14 (a) (ii))
- Advice** Engine Under Shield Damaged
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing Arm Front Bush (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing Arm Front Bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre 3mm

MOT #4

2019-10-14 08:28

MOT test number

764375123451

Result

✗ Failed

- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing Arm Front Bush (5.3.4 (a) (i))
- Advice** Engine Under Shield Damaged
- Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both Sides (1.1.14 (a) (ii))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing Arm Front Bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre 3mm
- Advice** Offside Front Play in steering rack inner joint(s)

MOT #3

2018-09-20 11:19

MOT test number

263644066593

Result

✓ Passed

- Advice** Items removed from driver's view prior to test
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



MOT #2	2017-10-19 08:35
MOT test number	454155558022
Result	✓ Passed
Advice	Engine under cover damaged
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1	2016-10-20 09:55
MOT test number	596947534015
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Rear tyres worn on edges



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
26 April 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	26 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	DU63JYW
Plate since	2019-03-28
Current registration	DU63JYW
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-11-26
Last registration	2024-04-15
Complete history	See info



Registration #1	2013-11-26	16 mi
Registration #2	2016-10-20	52.099 mi
Registration #3	2017-10-19	69.175 mi
Registration #4	2018-09-20	83.087 mi
Registration #5	2019-10-14	97.250 mi
Registration #6	2019-10-14	97.250 mi
Registration #7	2020-09-21	101.358 mi
Registration #8	2021-05-28	104.050 mi
Registration #9	2022-05-28	104.050 mi
Registration #10	2022-05-28	104.050 mi
Registration #11	2022-05-28	104.050 mi
Registration #12	2022-05-28	104.050 mi
Registration #13	2022-05-28	104.050 mi
Registration #14	2022-05-28	104.050 mi
Registration #15	2022-05-28	104.050 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	82%
Pedestrian	72%
Safety systems	71%
Overall rating	84%
Video	see crash video



Additional information

Number of seats	5
Engine number	NOT KNOWN