



report date: 2024-03-28

General information

| | |
|---------------------|--------------------|
| Make | BMW |
| Model | X1 SDRIVE20I SPORT |
| Colour | White |
| Year of manufacture | 2019 |
| Top speed | 140 mph |
| Gearbox | 7 speed automatic |

Engine & fuel consumption

| | |
|----------------------|---------------------|
| Power | 189 BHP |
| Max. torque | 280 Nm at 1.350 rpm |
| Engine capacity | 1.998 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption combined | 37.7 mpg |
| CO2 emission | 136 g/km |
| CO2 label | E |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-07-22 |
| Pictures | 31 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-03-28 |
| MOT pass rate | 67 % |
| MOT passed | 2 |
| Failed MOT tests | 1 |
| Total advice items | 4 |
| Total items failed | 1 |

| | |
|------------------|--|
| MOT #3 | 2023-03-28 13:34 |
| MOT test number | 709297823351 |
| Result | ✓ Passed |
| Next expiry date | 2024-03-28 |
| Advice | Front Brake pad(s) wearing thin close to wear sensor (1.1.13 (a) (ii)) |

| | |
|-----------------|--|
| MOT #2 | 2023-03-27 12:08 |
| MOT test number | 447394509337 |
| Result | ✗ Failed |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Fail | Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) |
| Advice | Front Brake pad(s) wearing thin close to wear sensor (1.1.13 (a) (ii)) |

| | |
|-----------------|--|
| MOT #1 | 2022-03-07 10:44 |
| MOT test number | 740272330879 |
| Result | ✓ Passed |
| Advice | Central Items removed from driver's view prior to test |



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✗
MOT

Expired:
28 March 2024

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 64 |
| MOT expiry date | 28 March 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|-------------------------------|------------|
| Vehicle class | 48 |
| Band | H |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this BMW had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-03-28 |
| Current registration | |
| Plate since | 2019-03-28 |

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 5 |
| First mileage registration | 2019-03-29 |
| Last registration | 2023-03-28 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2019-03-29 | 18 mi |
| Registration #2 | 2022-03-07 | 37.862 mi |
| Registration #3 | 2023-03-28 | 38.877 mi |
| Registration #4 | 2023-03-28 | 38.877 mi |
| Registration #5 | 2023-03-28 | 38.877 mi |

More info >



Car features

The BMW factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 87% |
| Children | 86% |
| Pedestrian | 64% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1821 mm |
| Height | 1598 mm |
| Length | 4439 mm |
| Max. allowed weight | 2065 kg |

Additional information

| | |
|-----------------|----------|
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | F127K063 |