



PEUGEOT



SJIOANR

report date: 2024-03-28

General information

Make	PEUGEOT
Model	PARTNER HDI TEPEE OUTDOOR
Colour	Grey
Year of manufacture	2010
Top speed	100 mph
0 - 60 mph	15.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	56.5 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





MOT history

MOT expiry date	2021-09-24
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	27
Total items failed	9

MOT #14	2020-09-25 12:43
MOT test number	325323913319
Result	✓ Passed
Next expiry date	2021-09-24
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Clutch pedal rubber missing

**MOT #13**

2020-09-25 08:53

MOT test number

761836375974

Result**✗ Failed**

- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Clutch pedal rubber missing

MOT #12

2019-05-09 14:11

MOT test number

315464818039

Result**✓ Passed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
- Advice** Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #11** 2019-05-08 14:54**MOT test number** 880249428632**Result** ✗ Failed**MAJOR** Offside Front Position lamp not working (4.2.1 (a))**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))**MAJOR** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Service brake binding but not excessively (1.2.1 (f))**MOT #10** 2018-05-08 16:32**MOT test number** 869672374545**Result** ✓ Passed**Advice** Rear exhaust corroded**MOT #9** 2018-05-08 12:15**MOT test number** 682794536756**Result** ✗ Failed**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2017-05-09 11:12**MOT test number** 725164776067**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #7** 2017-05-09 11:12**MOT test number** 852463100168**Result** ✗ Failed**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2016-04-28 14:20**MOT test number** 956367231215**Result** ✓ Passed**MOT #5** 2016-04-28 14:20**MOT test number** 909225414569**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper blade insecure (8.2.2)**MOT #4** 2015-04-30 12:46**MOT test number** 659900925100**Result** ✓ Passed**MOT #3** 2015-04-30 12:06**MOT test number** 569310825184**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)



MOT #2	2014-04-28 15:02
MOT test number	805638914149
Result	✓ Passed

MOT #1	2013-04-30 13:39
MOT test number	156610323100
Result	✓ Passed



Tax & MOT check

×

Untaxed

Tax expired:
30 September 2021

×

MOT

Expired:
24 September 2021

Tax status

Expired at 30 September

Days left

941 days too late

MOT expiry date

24 September 2021

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-08-31
Last registration	2020-09-25
Complete history	See info



Registration #1	2010-08-31	11 mi
Registration #2	2013-04-30	21.062 mi
Registration #3	2014-04-28	39.121 mi
Registration #4	2015-04-30	60.203 mi
Registration #5	2015-04-30	60.204 mi
Registration #6	2016-04-28	78.099 mi
Registration #7	2016-04-28	78.099 mi
Registration #8	2017-05-09	91.103 mi
Registration #9	2019-05-20	91.103 mi
Registration #10	2019-05-20	91.103 mi
Registration #11	2019-05-20	91.103 mi
Registration #12	2019-05-20	91.103 mi
Registration #13	2019-05-20	91.103 mi
Registration #14	2019-05-20	91.103 mi
Registration #15	2019-05-20	91.103 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1810 mm
Height	1803 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1599 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBBU3185836