



report date: 2024-03-29

General information

Make	VOLVO
Model	V50
Colour	Blue
Year of manufacture	2008
Gearbox	-

Engine & fuel consumption

Engine capacity	1.798 cc
Fuel type	Petrol
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-21
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2024-11-02
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	33
Total items failed	9

MOT #17	2023-11-03 13:27
MOT test number	294024949647
Result	✓ Passed
Next expiry date	2024-11-02
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #16	2022-09-27 11:00
MOT test number	114271326094
Result	✓ Passed

MOT #15	2021-06-30 11:26
MOT test number	684511147876
Result	✓ Passed
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Rear exhaust tail pipe mounting bracket corroded/broken but system is secure
Advice	Rear Exhaust has a minor leak of exhaust gases exhaust box pipe weld cracked/slight leak (6.1.2 (a))
Advice	Rear suspension components rusted

**MOT #14**

2021-06-29 14:21

MOT test number

369900153013

Result

✗ Failed

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Rear Brake pad(s) less than 1.5 mm thick brake pads worn close to metal from the inner side (1.1.13 (a) (ii))**Advice** Rear exhaust tail pipe mounting bracket corroded/broken but system is secure**Fail** Offside Front Tyre has ply or cords exposed inner edge worn to cords (5.2.3 (d) (ii))**Advice** Rear Exhaust has a minor leak of exhaust gases exhaust box pipe weld cracked/slight leak (6.1.2 (a))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened and offside rear discs scored/worn /lipped (strong advice) (1.1.14 (a) (ii))**Advice** Rear suspension components rusted**MOT #13**

2020-07-02 12:51

MOT test number

128182176099

Result

✓ Passed

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12**

2019-07-16 14:25

MOT test number

871910584645

Result

✓ Passed

Minor Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11** 2019-07-12 11:02**MOT test number** 111513988496**Result** ✗ Failed**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**MOT #10** 2018-07-21 10:41**MOT test number** 864355894770**Result** ✓ Passed**MOT #9** 2017-07-06 08:21**MOT test number** 482778016393**Result** ✓ Passed**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**MOT #8** 2017-07-06 08:21**MOT test number** 687065743457**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Pass with rectification** Offside Side repeater not working (1.4.A.2c)**MOT #7** 2016-07-13 16:48**MOT test number** 193100583440**Result** ✓ Passed**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)

**MOT #6** 2016-07-13 09:27**MOT test number** 409553318611**Result** ✗ Failed**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Fail** Nearside Rear Direction indicator incorrect colour bulb (1.4.A.2f)**Fail** Offside Side repeater not working (1.4.A.2c)**Fail** Offside Rear Direction indicator incorrect colour bulb (1.4.A.2f)**MOT #5** 2015-07-15 09:04**MOT test number** 557066695128**Result** ✓ Passed**Advice** Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Advice** Nearside Rear Rear reflector slightly damaged but function not impaired (1.5.1c)**MOT #4** 2014-07-19 11:40**MOT test number** 266390404286**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Upper Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

**MOT #3** 2013-07-31 13:03**MOT test number** 117042213218**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-08-25 15:18**MOT test number** 356878632411**Result** ✓ Passed**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**MOT #1** 2011-05-17 14:45**MOT test number** 225207131100**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
28 March 2024

✓

MOT

Expires:
2 November 2024

Tax status	Expired at 28 March 2024
Days left	33 days too late
MOT expiry date	2 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-06-09
Last registration	2023-11-03
Complete history	See info



Registration #1	2008-06-09	19 mi
Registration #2	2011-05-17	19.472 mi
Registration #3	2012-08-25	33.225 mi
Registration #4	2013-07-31	43.772 mi
Registration #5	2014-07-19	54.543 mi
Registration #6	2015-07-15	61.738 mi
Registration #7	2016-07-13	71.496 mi
Registration #8	2016-07-13	71.496 mi
Registration #9	2017-07-06	80.168 mi
Registration #10	2017-07-06	80.168 mi
Registration #11	2018-06-20	81.277 mi
Registration #12	2019-06-20	81.277 mi
Registration #13	2020-06-20	81.277 mi
Registration #14	2021-06-20	81.277 mi
Registration #15	2022-06-20	81.277 mi
Registration #16	2023-06-20	81.277 mi
Registration #17	2024-06-20	81.277 mi
Registration #18	2025-06-20	81.277 mi
Registration #19	2026-06-20	81.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Number of seats	4
Engine number	143891