



report date: 2024-03-29

General information

|                     |                    |
|---------------------|--------------------|
| Make                | VAUXHALL           |
| Model               | VECTRA SRI NAV 16V |
| Colour              | Silver             |
| Year of manufacture | -                  |
| Top speed           | 127 mph            |
| 0 - 60 mph          | 10.5 seconds       |
| Gearbox             | 5 speed Manual     |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 138 BHP             |
| Max. torque             | 167 Nm at 3.800 rpm |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 27.7 mpg            |
| Consumption extra urban | 50.4 mpg            |
| Consumption combined    | 38.7 mpg            |






Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-09-10                  |
| Pictures      | 18                          |
| Listing price | <a href="#">View report</a> |



source: cargurus.co.uk

**MOT history**

|                         |  |
|-------------------------|--|
| <b>MOT #23</b>          | 2022-09-27 10:07   |
| <b>MOT test number</b>  | 584357790611   |
| <b>Result</b>           | ✓ Passed   |
| <b>Next expiry date</b> | 2023-10-14   |
| <b>Advice</b>           | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| <b>Advice</b>           | Oil leak, but not excessive (8.4.1 (a) (i))                            |
| <b>Advice</b>           | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))                       |
| <b>Advice</b>           | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |

|                        |  |
|------------------------|--|
| <b>MOT #22</b>         | 2021-10-01 15:47   |
| <b>MOT test number</b> | 986779334903   |
| <b>Result</b>          | ✓ Passed   |
| <b>Advice</b>          | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |

|                        |  |
|------------------------|--|
| <b>MOT #21</b>         | 2021-10-01 14:13   |
| <b>MOT test number</b> | 797143112467   |
| <b>Result</b>          | ✗ Failed   |
| <b>Advice</b>          | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))       |
| <b>MAJOR</b>           | Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))                             |
| <b>Advice</b>          | Front Brake disc worn, but not excessively strongly recommend replacement (1.1.14 (a) (i)) |

|                        |   |
|------------------------|---|
| <b>MOT #20</b>         | 2020-10-15 14:12  |
| <b>MOT test number</b> | 632852082145  |
| <b>Result</b>          | ✓ Passed  |
| <b>Advice</b>          | All brake discs worn                                    |
| <b>Advice</b>          | Power steering pipe/hose has slight seepage (2.1.5 (a)) |
| <b>Advice</b>          | Oil leak, but not excessive Engine (8.4.1 (a) (i))      |

**MOT #19**

2020-10-15 12:55

**MOT test number**

559426062702

**Result****✗ Failed**

- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))
- Advice** All brake discs worn
- Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Front tyres getting low on the inner edges
- Advice** Power steering pipe/hose has slight seepage (2.1.5 (a))
- Advice** Offside Front Nail in tyre

**MOT #18**

2019-10-15 13:37

**MOT test number**

779537471305

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Centre exhaust blowing from join



MOT #17

2019-10-11 10:03

MOT test number

339936252963

Result

✖ Failed

- MAJOR** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Advice** Centre exhaust blowing from join
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- MAJOR** Offside Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Fuel system component leaking Filter casing corroded and leaking (6.1.3 (b) (i))



MOT #16

2018-10-11 14:34

MOT test number

759884554681

| Result |   | ✓ Passed |
|--------|---|----------|
| Advice | Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))  |          |
| Advice | Front Oil leak, but not excessive (8.4.1 (a) (i))   |          |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))   |          |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))                          |          |
| Advice | Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))                 |          |
| Advice | Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))                              |          |
| Advice | Front Items removed from driver's view prior to test  |          |
| Advice | Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))   |          |
| Minor  | Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |          |
| Advice | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))    |          |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))                           |          |
| Advice | Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))                  |          |

**MOT #15**

2018-10-09 09:23

**MOT test number**

447940584957

**Result****✗ Failed****Advice** Front Items removed from driver's view prior to test**DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear slight bind from brake**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Brake pipe excessively corroded front to rear x2 (1.1.11 (c))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14**

2017-10-10 10:33

**MOT test number**

497969391348

**Result****✓ Passed****Advice** Rear Brake pipe slightly corroded both (3.6.B.2c)

**MOT #13**

2016-10-10 10:14

**MOT test number**

799701124967

**Result**

✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Brake pipe slightly corroded front to rear x2 (3.6.B.2c)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #12**

2016-10-05 10:46

**MOT test number**

682954596251

**Result**

✗ Failed

- Advice** Brake pipe slightly corroded front to rear x2 (3.6.B.2c)
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #11**

2015-10-08 07:58

**MOT test number**

786319111065

**Result**

✓ Passed

- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view houseing (8.1.2a)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)





|                        |   |
|------------------------|---|
| <b>MOT #10</b>         | 2014-10-08 15:55                        |
| <b>MOT test number</b> | 839961284231                            |
| <b>Result</b>          | ✓ Passed                                |
| <b>Advice</b>          | Rear Brake pad(s) wearing thin (3.5.1g) |

|                        |   |
|------------------------|---|
| <b>MOT #9</b>          | 2014-10-07 16:38  |
| <b>MOT test number</b> | 239210984233  |
| <b>Result</b>          | ✗ Failed  |
| <b>Fail</b>            | Offside Rear coil spring broken (2.4.C.1a)                            |
| <b>Advice</b>          | Rear Brake pad(s) wearing thin (3.5.1g)                               |
| <b>Fail</b>            | Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) |

|                        |                  |
|------------------------|------------------|
| <b>MOT #8</b>          | 2013-10-01 17:34 |
| <b>MOT test number</b> | 617424173247     |
| <b>Result</b>          | ✓ Passed         |

|                        |  |
|------------------------|--|
| <b>MOT #7</b>          | 2013-09-27 15:46                                       |
| <b>MOT test number</b> | 539990873236   |
| <b>Result</b>          | ✗ Failed   |
| <b>Fail</b>            | Parking brake: efficiency below requirements (3.7.B.7) |

|                        |   |
|------------------------|---|
| <b>MOT #6</b>          | 2012-09-27 17:32  |
| <b>MOT test number</b> | 639421372290  |
| <b>Result</b>          | ✓ Passed  |
| <b>Advice</b>          | Offside Front Upper Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2) |
| <b>Advice</b>          | Offside Rear Tyre worn close to the legal limit (4.1.E.1)   |

**MOT #5** 2012-08-17 15:13**MOT test number** 236080732210**Result** ✗ Failed**Fail** Nearside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #4** 2011-06-27 15:45**MOT test number** 305278371138**Result** ✓ Passed**MOT #3** 2011-06-27 10:44**MOT test number** 236118671441**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Offside Front coil spring fractured (2.4.C.1a)**MOT #2** 2010-05-24 13:09**MOT test number** 170224340173**Result** ✓ Passed**MOT #1** 2010-05-24 11:10**MOT test number** 121794340120**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 15,200 |
| Auction value               | £ 15,200 |
| Average private trade value | £ 15,200 |

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

|                      |  |
|----------------------|--|
| Number of plates     | 1  |
| Current registration |  <b>VAUXH</b> |
| Plate since          | 2024-03-29   |
| Current registration |  <b>VAUXH</b> |
| Plate since          | 2024-03-29   |

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

|                   |             |
|-------------------|-------------|
| Finance company   | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type    | XXXXXXXX XX |
| Agreement term    | XXXXXXXX XX |
| Agreement number  | XXXXXXXX XX |
| Contact info      | XXXXXXXX XX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 25                       |
| First mileage registration | 2006-05-16               |
| Last registration          | 2022-09-27               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2006-05-16 | 13 mi     |
| Registration #2  | 2010-05-24 | 44.016 mi |
| Registration #3  | 2010-05-24 | 44.016 mi |
| Registration #4  | 2011-06-27 | 48.906 mi |
| Registration #5  | 2011-06-27 | 48.906 mi |
| Registration #6  | 2012-08-17 | 51.194 mi |
| Registration #7  | 2012-09-27 | 51.224 mi |
| Registration #8  | 2013-09-27 | 55.749 mi |
| Registration #9  | 2013-10-01 | 55.749 mi |
| Registration #10 | 2014-10-07 | 61.330 mi |
| Registration #11 | 2014-10-08 | 61.330 mi |
| Registration #12 | 2015-10-08 | 65.598 mi |
| Registration #13 | 2016-10-05 | 70.873 mi |
| Registration #14 | 2016-10-05 | 70.873 mi |
| Registration #15 | 2016-10-05 | 70.873 mi |
| Registration #16 | 2016-10-05 | 70.873 mi |
| Registration #17 | 2016-10-05 | 70.873 mi |
| Registration #18 | 2016-10-05 | 70.873 mi |
| Registration #19 | 2016-10-05 | 70.873 mi |
| Registration #20 | 2016-10-05 | 70.873 mi |
| Registration #21 | 2016-10-05 | 70.873 mi |
| Registration #22 | 2016-10-05 | 70.873 mi |
| Registration #23 | 2016-10-05 | 70.873 mi |
| Registration #24 | 2016-10-05 | 70.873 mi |
| Registration #25 | 2016-10-05 | 70.873 mi |



Safety ratings

|             |                                 |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆                           |
| Video       | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 2036 mm |
| Height              | 1460 mm |
| Length              | 4611 mm |
| Wheel base          | 2700 mm |
| Kerb weight         | 1346 kg |
| Max. allowed weight | 1885 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 61 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |
| Engine number      | 20GT0161              |