



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK200K SPORT
Colour	Black
Year of manufacture	2007
Top speed	144 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg
CO2 emission	212 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-07-13
Pictures	24
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-26
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	26
Total items failed	3

MOT #16	2023-07-24 10:21
MOT test number	828485868663
Result	✓ Passed
Next expiry date	2024-07-26

MOT #15	2022-07-27 15:16
MOT test number	544489779429

Result	✓ Passed
Advice	Nearside Front Brake pipe corroded, covered in grease or other material Starting to corrode (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material Starting to corrode (1.1.11 (c))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Brake pipe corroded, covered in grease or other material Starting to corrode (1.1.11 (c))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Rear Inner Brake disc worn, pitted or scored, but not seriously weakened Both rear inner faces of brake discs badly corroded (1.1.14 (a) (ii))

**MOT #14** 2021-12-11 10:00**MOT test number** 209182282233**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 245/40R17 91Y Avon (5.2.3 (d) (ii))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing 245/40R17 91Y Avon (5.2.3 (d) (ii))**MOT #13** 2020-10-24 11:47**MOT test number** 972880973052**Result** ✓ Passed**Advice** Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Tyre slightly damaged/cracking or perishing both slight perishing (5.2.3 (d) (ii))**MOT #12** 2019-10-17 11:33**MOT test number** 663478518000**Result** ✓ Passed**Minor** Central Front Windscreen damaged but not adversely affecting driver's view small chip only. (3.2 (a) (i))**MOT #11** 2018-10-02 08:51**MOT test number** 485373253817**Result** ✓ Passed**MOT #10** 2017-10-18 09:58**MOT test number** 149126845570**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases exhaust split but not leaking gas. (7.1.2)



MOT #9	2016-10-19 12:47
MOT test number	347254230945
Result	✓ Passed
Advice	Under trays fitted obscuring some testable items.

MOT #8	2015-10-20 15:16
MOT test number	893331287682
Result	✓ Passed
Advice	Centre rear exhaust support broken/corroded
Advice	Front brake disc worn, pitted or scored, but not seriously weakened both inner faces (3.5.1i)

MOT #7	2015-10-19 12:27
MOT test number	974890825646
Result	✗ Failed
Fail	Nearside Front coil spring broken (2.4.C.1a)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened both inner faces (3.5.1i)
Advice	Centre rear exhaust support broken/corroded

MOT #6	2014-09-29 10:12
MOT test number	138892174289
Result	✓ Passed
Notice	N/S/R Tyre split on inner side wall.
Notice	Exhaust hanger broken at rear section area.
Notice	Under-trays fitted obscuring some underside components
Notice	O/S/R Tyre split on inner side wall.
Notice	Front brake discs worn.

**MOT #5** 2013-10-02 10:03**MOT test number** 147595773242**Result** ✓ Passed**MOT #4** 2012-10-04 13:27**MOT test number** 866848172284**Result** ✓ Passed**MOT #3** 2012-09-21 10:43**MOT test number** 805815062270**Result** ✗ Failed**Fail** Nearside Rear Wheel stud(s) missing (4.2.A.1e)**Fail** Offside Rear Wheel stud(s) missing (4.2.A.1e)**MOT #2** 2011-09-27 08:46**MOT test number** 269700171232**Result** ✓ Passed**Notice** Rear tyres worn low**MOT #1** 2010-07-13 13:51**MOT test number** 154404690162**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
26 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	26 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-09-10
Last registration	2023-07-24
Complete history	See info



Registration #1	2007-09-10	13 mi
Registration #2	2010-07-13	51.419 mi
Registration #3	2011-09-27	62.576 mi
Registration #4	2012-09-21	67.763 mi
Registration #5	2012-10-04	68.033 mi
Registration #6	2013-10-02	73.854 mi
Registration #7	2014-09-29	77.270 mi
Registration #8	2015-10-19	79.397 mi
Registration #9	2015-10-20	79.405 mi
Registration #10	2016-05-20	80.277 mi
Registration #11	2016-05-20	80.277 mi
Registration #12	2016-05-20	80.277 mi
Registration #13	2016-05-20	80.277 mi
Registration #14	2016-05-20	80.277 mi
Registration #15	2016-05-20	80.277 mi
Registration #16	2016-05-20	80.277 mi
Registration #17	2016-05-20	80.277 mi
Registration #18	2016-05-20	80.277 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1665 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195531000472