





report date: 2024-03-28

#### General information

Make	FIAT
Model	DOBLO MYLIFE
Colour	Black
Year of manufacture	2012
Top speed	100 mph
0 - 60 mph	15.4 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	95 BHP
Max. torque	127 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	166 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



# Internet history

#### Entry 1

Date 2021-01-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



# MOT history

MOT expiry date	2025-02-28
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	25
Total items failed	3

MOT #14	2024-02-29 09:53
MOT test number	396389750682
Result	<b>✓</b> Passed
Next expiry date	2025-02-28
Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #13	2023-02-16 11:26	5
MOT test	number 456435625998	3
Result	✓ Passed	k
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #12	2022-02-16 10:20
MOT test	number 880175199877
Result	✓ Passed
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11	2021-03-01 14:40
MOT test number	663617712731
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/13



MOT #10 2020-07-16 15:45 **MOT test number** 115476654432 Result ✓ Passed MOT #9 2020-07-07 13:27 **MOT test number** 833813657396 Result × Failed **Advice** Unable to see the front inner pads clearly Fail Central Exhaust has a major leak of exhaust gases (6.1.2 (a)) Advice Both rear tyres cracked and wearing low Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** 

MOT #8	2019-05-24 08:42
MOT test number	116269696174
Result	✓ Passed
MOT #7	2018-04-19 07:48
MOT test number	567641847363
Result	✓ Passed

MOT #6	2017-06-26 12:28
MOT test number	558830704262
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/13



Advice

**Advice** 

Small chips on windscreen

YY61JNO report date: 2024-03-28

MOT test number

Result

Advice

Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened slightly (3.5.1i)

Advice

Rear belt not checked due to wheel chair convertion

Advice

Offside Front Upper strut mounting seized slightly

Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT test number

508714510441

Result

Advice

Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Rear seats belts not checked due to wheel chair conversion

MOT #3		2016-01-25 13:31
MOT test	number	891543998077
Result		<b>×</b> Failed
Advice	Offside Front Inner brake disc worn, pitted or scored, but not seriously we	eakened (3.5.1i)
Advice	Front and rear exhaust clamps corroded and braking up	
Advice	Nearside Front Inner brake disc worn, pitted or scored, but not seriously	weakened (3.5.1i)
Advice	Rear seats belts not checked due to wheel chair conversion	
Fail Nearside Front coil spring broken (2.4.C.1a)		

CarCheck.co.uk page 5/13



MOT #2


MOT test number

445523415092

Result

Notice Front discs corroded

Notice Under-trays fitted obscuring some underside components



CarCheck.co.uk page 6/13





## Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	28 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>I</u>		e?
manage of the same		
***************************************		
********		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		9
Current registration	UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-02-01
Last registration	2024-02-29
Complete history	See info



Registration #1	2012-02-01	21 mi
Registration #2	2015-01-12	16.882 mi
Registration #3	2015-01-13	16.882 mi
Registration #4	2016-01-25	23.673 mi
Registration #5	2016-01-26	23.673 mi
Registration #6	2017-01-09	27.493 mi
Registration #7	2017-06-26	28.299 mi
Registration #8	2018-04-19	29.457 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		19.377 es

More info >

CarCheck.co.uk page 12/13



## Car features

50225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4390 mm
Wheel base	2755 mm
Kerb weight	1340 kg
Max. allowed weight	1940 kg

## Additional information

Fuel tank capacity	60 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2
Engine number 1670202