



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D DRIVE SE LUX
Colour	Silver
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 2

Date	2021-06-25
Pictures	27
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-06-22
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



## MOT history

MOT expiry date	2024-08-07
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	27
Total items failed	8

MOT #14	2023-07-20 08:24
MOT test number	811468185978
Result	✓ Passed
Next expiry date	2024-08-07

MOT #13	2022-07-18 06:09
MOT test number	541557930917
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12	2021-08-06 11:09
MOT test number	775794519174
Result	✓ Passed

MOT #11	2021-08-04 13:56
MOT test number	505515536748
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10**

2020-07-30 08:31

**MOT test number**

735344350534

**Result**

✓ Passed

**Advice** Offside & Nearside rear tyre tread depths low on inner edges in areas of secondary tread.**Advice** Vehicle fitted with under trays partially obscuring inspection of some components.**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #9**

2019-07-15 14:05

**MOT test number**

637191779912

**Result**

✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Nail in tyre**MOT #8**

2018-08-08 15:17

**MOT test number**

371697385304

**Result**

✓ Passed

**MOT #7**

2018-08-07 13:27

**MOT test number**

377037143276

**Result**

✗ Failed

**Advice** Brake pad(s) wearing thin Front and Rear (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Tyre tread depth below requirements of 1.6mm 205/50/17 (5.2.3 (e))

**MOT #6**

2017-12-20 15:22

**MOT test number**

201652509659

**Result**

✓ Passed

- Advice** Both front tyres badly worn on inner edges
- Advice** Windscreen insecure
- Advice** Nearside Front Tyre perished on outer wall
- Advice** Nearside Rear Tyre mis-shaped on inner edge

**MOT #5**

2017-12-19 14:31

**MOT test number**

741278030875

**Result**

✗ Failed

- Advice** Nearside Rear Tyre mis-shaped on inner edge
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Windscreen insecure
- Fail** Offside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Both front tyres badly worn on inner edges
- Advice** Vehicle under tray insecure
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Front Tyre perished on outer wall

**MOT #4**

2016-12-29 09:41

**MOT test number**

155399796411

**Result**

✓ Passed

- Advice** Under tray fitted
- Advice** Offside Front tyre wearing on inner edge



MOT #3	2016-01-07 12:36
MOT test number	136021499625
Result	✓ Passed

MOT #2	2016-01-07 12:36
MOT test number	553062134625
Result	✗ Failed
Pass with rectification	Offside Rear Registration plate lamp not working (1.1.C.1d)
Pass with rectification	Front Headlamp cleaning device inoperative (1.7.2)

MOT #1	2014-09-01 10:27
MOT test number	147544744206
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
7 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	7 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-09-28
Last registration	2023-07-20
Complete history	<a href="#">See info</a>



Registration #1	2011-09-28	17 mi
Registration #2	2014-09-01	27.168 mi
Registration #3	2016-01-07	38.746 mi
Registration #4	2016-01-07	38.746 mi
Registration #5	2016-12-29	45.276 mi
Registration #6	2017-12-19	54.808 mi
Registration #7	2017-12-20	54.808 mi
Registration #8	2018-08-07	60.908 mi
Registration #9	2018-08-08	60.908 mi
Registration #10	2019-05-29	65.377 mi
Registration #11	2019-05-29	65.377 mi
Registration #12	2019-05-29	65.377 mi
Registration #13	2019-05-29	65.377 mi
Registration #14	2019-05-29	65.377 mi
Registration #15	2019-05-29	65.377 mi
Registration #16	2019-05-29	65.377 mi
Registration #17	2019-05-29	65.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1760212