



report date: 2024-03-28

General information

Make	VOLVO
Model	S60 D3 SE
Colour	Black
Year of manufacture	2012
Top speed	137 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	68.9 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D






Internet history

Entry 1

Date	2022-06-10
Pictures	5
Listing price	View report



source: cargurus.co.uk





MOT history

MOT expiry date	2024-06-23
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #10	2023-06-24 08:50
MOT test number	945057702696
Result	✓ Passed
Next expiry date	2024-06-23
Advice	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Tyre Wearing on edge

MOT #9	2022-06-14 14:38
MOT test number	789016135530
Result	✓ Passed

MOT #8	2021-08-26 09:01
MOT test number	872139316558
Result	✓ Passed

**MOT #7** 2021-08-25 09:09**MOT test number** 851947851547**Result** ✗ Failed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- MAJOR** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Play in steering rack inner joint(s)

MOT #6 2020-08-26 13:12**MOT test number** 644768928567**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2019-09-02 13:55**MOT test number** 844010094071**Result** ✓ Passed

- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #4 2018-09-04 13:46**MOT test number** 180898796121**Result** ✓ Passed**MOT #3** 2017-09-13 08:53**MOT test number** 997315753586**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #2	2016-09-22 08:30
MOT test number	192864482277
Result	✓ Passed

MOT #1	2015-09-02 13:12
MOT test number	977129248797
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
23 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	23 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	AK620UE
Plate since	2019-09-28
Current registration	AK620UE
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-09-29
Last registration	2023-06-24
Complete history	See info



Registration #1	2012-09-29	23 mi
Registration #2	2015-09-02	23.489 mi
Registration #3	2016-09-22	30.786 mi
Registration #4	2017-09-13	38.228 mi
Registration #5	2018-09-04	45.113 mi
Registration #6	2019-09-02	52.319 mi
Registration #7	2020-09-02	59.525 mi
Registration #8	2021-09-02	66.731 mi
Registration #9	2022-09-02	73.937 mi
Registration #10	2023-03-24	81.143 mi
Registration #11	2023-06-24	88.349 mi
Registration #12	2023-06-24	88.349 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1574 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	1099062