





report date: 2024-03-29

General information

Make	BMW
Model	123 123D M SPORT
Colour	Black
Year of manufacture	2008
Top speed	148 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	201 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	Е



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2025-04-19
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	20
Total items failed	7

MOT #18	2024-04-20 10:11	
MOT test number	342607503268	
Result	✓ Passed	
Next expiry date	2025-04-19	
Advice Oil leak, but not excessive engine (8.4.1 (a) (i))		
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))		

MOT #17	2024-04-01 13:45	
MOT test number	108477655023	
Result	X Failed	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple (4.7.1 (b) (i))	lamps or light sources	
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))		
Advice Nearside Rear Shock absorbers has slight external damage to the casing	g (5.3.2 (b))	
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))		
Fail Nearside Headlamp aim too high (4.1.2 (a))		
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))		
Advice Offside Rear Shock absorbers has slight external damage to the casing ((5.3.2 (b))	
Fail Front Service brake excessively fluctuating (1.2.1 (e))		

CarCheck.co.uk page 2/12



MOT #16 2023-03-23 13:54

MOT test number 787803346112

Result \rightarrow Passed

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15 2022-03-18 16:21

MOT test number 375575859840

Result \(\sqrt{Passed} \)

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #14 2021-03-12 15:13

MOT test number 669628875072

Result ✓ Passed

MOT #13 2020-03-19 13:22

MOT test number 407106064185

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12 2019-03-22 16:55

MOT test number 927775211964

Result
✓ Passed

CarCheck.co.uk page 3/12



MOT #11

MOT test number

976175966431

Result

Control Description (Control Description (Con

Pass with rectification

Central Rear Vehicle Identification Number not legible (0.2 (b))

Pass with rectification

Fail

Offside Rear rear brake binding (3.7.B.1)

Central Front Vehicle Identification Number not legible (0.2 (b))

 MOT #10
 2018-03-19 17:48

 MOT test number
 803982678265

 Result
 ✓ Passed

 MOT #9
 2018-03-16 14:56

 MOT test number
 198685702794

 Result
 X Failed

MOT #8 2017-07-06 09:56

MOT test number 842942446926

Result ✓ Passed

 MOT #7
 2016-09-20 09:06

 MOT test number
 291046663230

 Result
 ✓ Passed

MOT #6

MOT test number

655109498348

Result

Advice Rear brake disc, inner faces, corroded.

Advice Wiper blades, poor wipe

CarCheck.co.uk page 4/12



MOT #5 2014-10-22 14:52 MOT test number 895815194204

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2013-10-24 11:44

MOT test number 197457593200

Result ✓ Passed

MOT #3 2012-10-03 13:43

MOT test number 198857072249

Result \rightarrow Passed

MOT #2 2012-10-03 13:43

MOT test number 307187072203

Result X Failed

Pass with rectification Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Pass with rectification Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1 2011-10-26 10:05

MOT test number 425379591265

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	19 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report I	
manage of the same	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	UK NEZ
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-10-13
Last registration	2024-04-20
Complete history	See info



Registration #1	2008-10-13	13 mi
Registration #2	2011-10-26	17.718 mi
Registration #3	2012-10-03	24.476 mi
Registration #4	2013-10-24	34.351 mi
Registration #5	2014-10-22	40.442 mi
Registration #6	2015-10-01	48.544 mi
Registration #7	2016-09-20	55.738 mi
Registration #8	2017-07-06	61.313 mi
Registration #9	2018-03-16	64.545 mi
Registration #10		11.777 es
Registration #11		71.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1748 mm
Height	1423 mm
Length	4360 mm
Wheel base	2660 mm
Kerb weight	1495 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	51
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 12/1

Number of axles 2

Engine number 93286766