



report date: 2024-03-29

General information

Make	VOLVO
Model	S90 T5 R-DESIGN EDITION
Colour	Grey
Year of manufacture	2019
Top speed	145 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	246 BHP
Max. torque	350 Nm at 1.800 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Petrol
Consumption combined	20.0 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 3

Date	2021-07-26
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 2

Date	2021-07-09
Pictures	0
Listing price	View report

source: [heycar.co.uk](#)

Entry 1

Date	2021-07-07
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-05-02
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	13
Total items failed	0

MOT #4	2024-04-05 10:00
MOT test number	747444096106
Result	✓ Passed
Next expiry date	2025-05-02

MOT #3	2023-04-28 15:24
MOT test number	654453786806
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords side wall (5.2.3 (d) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #2** 2023-04-28 08:25**MOT test number** 942846154182**Result** ✗ Failed

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords side wall (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Nail in tyre

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2022-04-18 13:12**MOT test number** 292081832135**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
2 May 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	2 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
First licence fee (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2019-05-03
Last registration	2024-04-05
Complete history	See info



Registration #1	2019-05-03	23 mi
Registration #2	2019-05-03	25,377 mi
Registration #3	2019-05-03	25,377 mi
Registration #4	2019-05-03	25,377 mi
Registration #5	2019-05-03	25,377 mi
Registration #6	2019-05-03	25,377 mi
Registration #7	2019-05-03	25,377 mi
Registration #8	2019-05-03	25,377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.


S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	84%
Pedestrian	74%
Safety systems	76%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1916 mm
Height	1437 mm
Length	4761 mm
Max. allowed weight	2240 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	2955564