





report date: 2024-03-29

#### General information

Make	NISSAN
Model	ELGRAND
Colour	White
Year of manufacture	2006
Gearbox	-

# Engine & fuel consumption

Engine capacity	2.490 cc
Fuel type	Petrol



CarCheck.co.uk page 1/11



report date: 2024-03-29

## Internet history


#### Entry 1

Date 2021-05-20

Pictures 35

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



WU56ANV report date: 2024-03-29

MOT history

MOT expiry date	2024-07-20
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	12
Total items failed	11

MOT #5	2023-07-19 15:34
MOT test number	791732464823
Result	✓ Passed
Next expiry date	2024-07-20
Minor Nearside Front Suspension arm ball joint dust cover severely deteriorate	d (5.3.4 (b) (i))

MOT #4	2023-07-18 13:11
MOT test number	731054412487
Result	<b>×</b> Failed
Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2022-07-21 15:37

MOT test number 216025082677

**Result** 
✓ Passed

**Advice** Vehicle fitted with 4 new tyres of commercial type, the speed rating is lower than the manufactures specification

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #2 2022-06-06 10:28

**MOT test number** 884542964743

Result X Failed

**Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))

**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front slight brake lagg

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Emissions not tested test aborted temperature guage in red and warning lamp on (8.2.1.2 (d))

Fail Front Registration plate does not conform to the specified requirements (0.1 (d))

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Advice** Vehicle fit with 4 new tyres of commercial type and lower speed rating from manufactures design.

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

MOT #1 2021-01-12 15:03

**MOT test number** 931667989437

**Result** ✓ Passed

CarCheck.co.uk page 5/11



report date: 2024-03-29

#### Tax & MOT check



Days left 215

MOT expiry date 20 July 2024

Full MOT history See MOT history

CarCheck.co.uk page 6/11



report date: 2024-03-29

#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this NISSAN had different number plates. about of pliates faste since

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2006-11-01
Last registration	2023-07-19
Complete history	See info



Registration #1	2006-11-01	18 mi
Registration #2	2021-01-12	77.100 mi
Registration #3		11.777 es
Registration #4	2022-06-06	152.967 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

#### Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

## Additional information

Number of seats	8
Engine number	VQ25

CarCheck.co.uk page 11/11