





report date: 2024-03-29

General information

M. I.	ALIDI
Make	AUDI
Model	Q7 TDI QUATTRO S LINE
Colour	Silver
Year of manufacture	2007
Top speed	134 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	229 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	19.3 mpg
Consumption extra urban	34.0 mpg
Consumption combined	26.9 mpg
CO2 emission	279 g/km
CO2 label	М



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-07-24

Pictures 18

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-07-22

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2024-10-06
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #14	2023-10-07 10:09
MOT test number	975782360641
Result	✓ Passed
Next expiry date	2024-10-06
Advice Front Lower Suspension arm pin or bush worn but not resulting in excess lower (5.3.4 (a) (i)) Advice Front Oil leak, but not excessive top to bottom (8.4.1 (a) (i))	sive movement both side

MOT #13	2022-10-05 15:50
MOT test number	641695060797
Result	✓ Passed

MOT #12	2021-08-23 13:49
---------	------------------

MOT test number 231193442146

Result
✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement wishbone arm bush (5.3.4 (a) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement wishbone arm bush (5.3.4 (a) (i))

CarCheck.co.uk page 3/12



MOT #11 2021-08-22 13:01

MOT test number 521350505057

Result X Failed

Fail Nearside Windscreen wiper not working blade arm damaged (3.4 (a))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement wishbone arm bush (5.3.4 (a) (i))

Fail Nearside Front Windscreen wiper missing (3.4 (a))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement wishbone arm bush (5.3.4 (a) (i))

MOT #10 2019-10-29 10:30

MOT test number 694090118196

Result ✓ Passed

MOT #9 2018-10-29 09:15

MOT test number 803431542589

Result
✓ Passed

MOT #8 2017-10-24 08:16

MOT test number 443044755251

Result \(\sqrt{Passed} \)

Advice Front Anti-roll bar corroded but not seriously weakened (2.4.G.1)

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)

MOT #7 2016-05-12 09:52

MOT test number 933380600763

Result \rightarrow Passed

Advice Items removed from drivers view prior to test

CarCheck.co.uk page 4/12



MOT test number

MOT test number

Result

MOT #1

Result

KR07TLZ report date: 2024-03-29

765995841080

2010-04-22 11:35 510402210102

✓ Passed

✓ Passed

MOT #6	2016-04-19 11:35
MOT test number	293642790152
Result	✓ Passed
MOT #5	2015-03-18 14:40
MOT test number	159817675445
Result	✓ Passed
MOT #4	2014-03-08 12:03
MOT test number	137917164429
Result	✓ Passed
Notice H/brake effort low 16%	
MOT #3	2012-03-21 15:21
MOT test number	109551582066
Result	✓ Passed
MOT #2	2011-02-14 12:19

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	6 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report I		ve?

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-05-29
Last registration	2023-10-07
Complete history	See info



Registration #1	2007-05-29	19 mi
Registration #2	2010-04-22	34.112 mi
Registration #3	2011-02-14	40.225 mi
Registration #4	2012-03-21	47.810 mi
Registration #5	2014-03-08	56.932 mi
Registration #6	2015-03-18	64.365 mi
Registration #7	2016-04-19	70.823 mi
Registration #8	2016-05-12	71.449 mi
Registration #9	2017-10-24	83.651 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1983 mm
Height	1737 mm
Length	5086 mm
Wheel base	3002 mm
Kerb weight	2325 kg
Max. allowed weight	3120 kg

Additional information

Fuel tank capacity	100
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/1