





General information

| Make | PEUGEOT |
|---------------------|---------------------------------------|
| Model | EXPERT HDI 1000 L1H1 PROFESSIONAL P/V |
| Colour | White |
| Year of manufacture | 2015 |
| Top speed | 90 mph |
| 0 - 60 mph | 17.1 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 90 BHP |
|-------------------------|---------------------|
| Max. torque | 180 Nm at 1.500 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 35.8 mpg |
| Consumption extra urban | 45.6 mpg |
| Consumption combined | 42.2 mpg |
| CO2 emission | 177 g/km |
| CO2 label | 1 |







Internet history

Entry 1

Date Pictures 2021-08-11

11

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2025-03-07 |
|--------------------|------------|
| MOT pass rate | 64 % |
| MOT passed | 7 |
| Failed MOT tests | 4 |
| Total advice items | 20 |
| Total items failed | 7 |

| MOT #11 | | 2024-03-08 18:16 |
|---------------------------------|--|------------------|
| MOT test number | | 161727557481 |
| Result | | Passed |
| Next expiry date | | 2025-03-07 |
| Advice Nearside Front Lower T | Tyre worn close to legal limit/worn on edge (5 | 5.2.3 (e)) |
| Advice Exhaust mounting defe | ective (6.1.2 (a)) | |
| Advice Offside Front Inner Tyre | e worn close to legal limit/worn on edge (5.2. | .3 (e)) |

| MOT #10 | 2023-02-04 12:41 |
|-----------------|------------------|
| MOT test number | 496427171241 |
| Result | ✓ Passed |

| MOT #9 | 9 | 2023-01-26 15:05 |
|---------------|---|------------------|
| MOT te | est number | 254853879612 |
| Result | | 🗙 Failed |
| Fail (ii)) | Offside Front Prop shaft joint constant velocity boot no longer prevents the ingress of | dirt (6.1.7 (g) |



| LO64NTA |
|-------------------------|
| report date: 2024-03-28 |

| MOT #8 | | 2022-03-03 15:42 | |
|---|--|------------------|--|
| MOT test n | number | 825437347649 | |
| Result | | ✓ Passed | |
| Advice | Nearside Front Play in steering rack inner joint(s) | | |
| Advice | Nearside Front Wheel bearing has slight play (5.1.3 (a) (i)) | | |
| Advice | Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | | |
| Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) | | | |
| | | | |
| MOT #7 | | 2022-03-02 08:51 | |
| MOT test n | number | 850942364487 | |
| Result | | 🗙 Failed | |
| | | | |

| Pass with rectification | Nearside Windscreen washer provides insufficient washer liquid (3.5 (a)) | |
|--|--|--|
| Minor Nearside From | t Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) | |
| Advice Front Brake | disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | |
| Fail Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c)) | | |
| Advice Nearside Front Play in steering rack inner joint(s) | | |
| Pass with rectification | Offside Windscreen washer provides insufficient washer liquid (3.5 (a)) | |
| Advice Nearside Fro | nt Wheel bearing has slight play (5.1.3 (a) (i)) | |

| MOT #6 | 2021-02-15 17:09 |
|---|------------------|
| MOT test number | 442118253530 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |



| LO64NTA |
|-------------------------|
| report date: 2024-03-28 |

| MOT #5 | 2020-01-21 13:36 |
|---|------------------|
| MOT test number | 880165524148 |
| Result | ✓ Passed |
| Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| | |
| MOT #4 | 2020-01-17 11:09 |

MOT test number

| MOT test number | 547075665054 | |
|--|--------------|--|
| Result | 🗙 Failed | |
| Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | | |
| Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) | | |
| Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii)) | | |
| Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b |) (ii)) | |

| MOT #3 | 2019-01-18 10:57 |
|--|----------------------|
| MOT test number | 860031492717 |
| Result | ✓ Passed |
| Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or (b) (i)) | light sources (4.7.1 |

| MOT #2 | 2019-01-18 09:58 |
|---|-------------------------|
| MOT test number | 800384699405 |
| Result | 🗙 Failed |
| FailOffside Front Headlamp not working on main beam (4.1.1 (a) (ii))MinorNearside Registration plate lamp inoperative in the case of multiple lamps (b) (i)) | or light sources (4.7.1 |





| MOT #1 | 2018-01-22 17:14 |
|----------------------|------------------|
| MOT test number | 799884409110 |
| Result | ✓ Passed |
| Advice Wipers smeary | |



Tax & MOT check

| X Untaxed Tax expired: 1 February 2024 | ✓ MOT Expires: 7 March 2025 |
|---|--------------------------------------|
| Tax status | Expired at 1 February 2024 |
| Days left | 88 days too late |
| MOT expiry date | 7 March 2025 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---|
| Date | |
| Category | 4. DEM PE |
| Туре | |
| Damage 2 | Annet |
| Date | No. Contraction of the second |
| Category | AMP |
| Туре | |

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 6.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 11 711 |





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| ********** | |
| ******* | |
| ****** | |
| ********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this PEUGEOT had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2015-01-22 |
| Last registration | 2024-03-08 |
| Complete history | See info |



| Registration #1 | 2015-01-22 | 11 mi |
|------------------|------------|------------|
| Registration #2 | 2018-01-22 | 103.350 mi |
| Registration #3 | 2019-01-18 | 134.849 mi |
| Registration #4 | 2019-01-18 | 134.849 mi |
| Registration #5 | 2020-01-17 | 159.965 mi |
| Registration #6 | 2020-01-21 | 160.127 mi |
| Registration #7 | 2021-02-15 | 188.428 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.117 esi |
| Registration #11 | | 11.117 esi |
| Registration #12 | | 11.777 mi |
| Registration #13 | | 11.117 mi |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| 50501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 59% |
| Children | 86% |
| Pedestrian | 26% |
| Safety systems | 26% |
| Overall rating | 54% |
| Video | see crash video |



| Dimensions & weight | |
|---------------------------------|------------------------|
| Width | 2194 mm |
| Height | 1980 mm |
| Length | 4805 mm |
| Kerb weight | 1780 kg |
| Max. allowed weight | 2661 kg |
| Additional information | |
| Fuel tank capacity | 80 I |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 3 |
| Engine number CarCheck.co.uk | JBDF0073073 page 13/13 |