



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Black
Year of manufacture	2014
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-01-30
Pictures	3
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-02-08
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	16
Total items failed	6

MOT #11	2024-02-09 16:29
MOT test number	199623325783
Result	✓ Passed
Next expiry date	2025-02-08

MOT #10	2024-02-09 13:03
MOT test number	896969229581
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #9	2023-01-27 11:08
MOT test number	387813251095
Result	✓ Passed

MOT #8	2022-02-04 17:56
MOT test number	753826074004
Result	✓ Passed
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #7** 2021-06-16 13:30**MOT test number** 503079463001**Result** ✓ Passed

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #6** 2020-03-21 17:07**MOT test number** 310418649068**Result** ✓ Passed

**Advice** Nearside Rear Nail in tyre

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm rear bush (5.3.4 (a) (i))

**MOT #5** 2020-03-21 10:28**MOT test number** 481747415810**Result** ✗ Failed

**Fail** Offside Front Suspension arm pin or bush excessively worn lower arm rear bush (5.3.4 (a) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Rear Nail in tyre

**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))

**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm rear bush (5.3.4 (a) (i))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2019-03-07 12:50**MOT test number** 915441589211**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge near wear markers (5.2.3 (e))**MOT #3** 2019-03-07 12:50**MOT test number** 102294916408**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge near wear markers (5.2.3 (e))**MOT #2** 2018-03-22 13:08**MOT test number** 272222625983**Result** ✓ Passed**MOT #1** 2017-03-14 15:27**MOT test number** 982772991967**Result** ✓ Passed**Advice** Front blades smearing



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
8 February 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	338
<b>MOT expiry date</b>	8 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	WJ14YWP
Plate since	2019-03-28
Current registration	WJ14YWP
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-24
Last registration	2024-02-09
Complete history	<a href="#">See info</a>



Registration #1	2014-03-24	25 mi
Registration #2	2017-03-14	26.532 mi
Registration #3	2018-03-22	37.108 mi
Registration #4	2019-03-07	46.810 mi
Registration #5	2019-03-07	46.810 mi
Registration #6	2020-03-21	53.244 mi
Registration #7	2020-03-21	53.244 mi
Registration #8	2024-02-09	53.244 mi
Registration #9	2024-02-09	53.244 mi
Registration #10	2024-02-09	53.244 mi
Registration #11	2024-02-09	53.244 mi
Registration #12	2024-02-09	53.244 mi
Registration #13	2024-02-09	53.244 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 294843K LNQ